

30 015-03223

J-33 17-29

Webb Oil Co.

C - State #4

Tops

T. SALT - 350'

B. SALT - 805'

* Circulate cement to surface from 370' inside + outside
2" csg.

* Squeeze 100 sx cement Plug 850' - 750'. TAG

* Perf. 5" csg. 850' + 370'

* 25 sx cement Plug 2000' - 1900'

* 25 sx cement Plug 2400' - 2300'

* Spot 10 sx cement on CIBP 2935' - 2885'

* Run + set CIBP @ 2935'. Circ. gel.

8 5/8"

370'

w/25 sx

5"

2985'

w/125 sx