

PLUGS AND ADAPTERS

Heaving plug—Material _____ Length _____ Depth set _____
 Adapters—Material _____ Size _____

SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
5"		Nitro Glycoline	210	6/23	25.3 - 25.6	25.3

TOOLS USED

Rotary tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet
 Cable tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet

DATES

_____, 19____ Put to producing 6/30/44, 19____

The production for the first 24 hours was _____ barrels of fluid of which 100 % was oil; _____ %
 emulsion; _____ % water; and _____ % sediment. Gravity, °Bé. _____

If gas well, cu. ft. per 24 hours _____ Gallons gasoline per 1,000 cu. ft. of gas _____

Rock pressure, lbs. per sq. in. _____

EMPLOYEES

J. L. Lawrence, Driller C. L. Brown, Driller
H. A. Masterson, Driller W. A. Brown, Driller

FORMATION RECORD

FROM—	TO—	TOTAL FEET	FORMATION
0	2	2	Soil
2	20	18	Caliche
20	60	40	Red sand & gravel
60	65	5	Red shale
65	70	5	Limestone
70	155	85	Anhy
155	165	10	White chalk lime
165	195	30	Red shale
195	205	10	Anhy
205	210	5	Red shale
210	220	10	Anhy
220	265	45	Red shale
265	280	15	Anhy
280	325	45	Red
325	340	15	Red sand
340	365	25	Red shale
365	375	10	Salt
375	430	55	Salt & Anhy
430	565	135	Salt
565	575	10	Anhy
575	660	85	Salt
660	725	65	Salt & Potash
725	745	20	Salt
745	900	155	Anhy

(OVER)

FORMATION RECORD—CONTINUED