

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVED  
OFFICE FOR NUMB.  
OF COPIES REQUIRED  
(Other instructions on reverse  
side)

BLM Roswell District  
Modified Form No.  
NM060-3160-4

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC-028775-A	
2. NAME OF OPERATOR Southland Royalty Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME COMMISSION	
3. ADDRESS OF OPERATOR P.O. Box 51810, Midland, TX 79710-1810		7. UNIT AGREEMENT NAME Robinson Jackson Unit	
3a. AREA CODE & PHONE NO. (915)688-6800		8. FARM OR LEASE NAME RJU Tract 1A	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1295' FNL & 25' FEL		9. WELL NO. 16	
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson 7R,QN	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3560' GL		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 34, 17S, 29E	
		12. COUNTY OR PARISH Eddy	13. STATE NM

**Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data**

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU RIH w/2 7/8" tubing and bit to 2960'. RIH w/gauge ring and junk basket to 2930'  
RIH w/7"-23# CICR and set @ 2930'. Test tubing to 1500 psi. Cement sq. Grayburg Jackson open hole interval w/50 sxs Class C. Pull out of retainer and dump 6 sxs Class C atop same. Displace hole w/10ppg gelled brine.

RIH w/7" CIBP and set @ 2390'. Lay 25 sxs Class C CMT atop same.

RIH w/4" casing gun and perforate from 810'-811' w/4JHPF. RIH w/7" CICR and set @ 710'. Test tubing to 1000 psi. Cement w/30sxs Class C below retainer. Drop 6 sxs Class C atop same.

RIH w/4" casing gun and perforate 500'-501' w/4 JHPF.

Establish circulation down 7" casing. Displace hole w/fresh water. Mix and pump 150 sxs Class C cement and circulate to surface.

Cut off casing 3' below surface and place abandonment maker as per regulations.

Restore location as directed.

18. I hereby certify that the foregoing is true and correct

SIGNED \_\_\_\_\_ TITLE PRODUCTION ASSISTANT DATE 6/22/93

(This space for Federal or State office use)

(ORIG. SGD) DAVID R. GLASS

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JUL 10 1993

CONDITIONS OF APPROVAL, IF ANY:

**SEE ATTACHED**

**\*See Instructions on Reverse Side**

# MERIDIAN OIL

FIELD: Robinson Jackson 7RV8, QN, SA

DATE SPUD: 02/08/50 COMP: 02/31/50


LEASE: RJU Tract 1A

WELL NO. 18

ELEVATION: 3,560' G.L. / Loge Mass. 1/ GL

LOCATION: 129° FNL & 25° FEL: SEC. 34, T-17-S, R-29-E

Eddy County, New Mexico



# MERIDIAN OIL

FIELD: Robinson Jackson 7RVS, QN, SA


DATE SPUD: 02/09/50 COMP: 03/31/50

LEASE: RJU Tract 1A WELL NO. 18

ELEVATION: 3,580' G.L. / Loge Mass. 1/4L

LOCATION: 1295' FNL & 25' FEL; SEC. 34, T-17-S, R-29-E

Eddy County, New Mexico



BUREAU OF LAND MANAGEMENT  
CARLSBAD RESOURCE AREA

Permanent Abandonment of Wells on Federal Lands

Conditions of Approval

[REDACTED]

2. Notification: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Eddy County call (505)887-6544 ; for wells in Lea County call (505) 393-3612.

3. Blowout Preventers: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet ; and a 5M system for a well not deeper than 22,727 feet.

4. Mud Requirement: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks ( 50 pounds each ) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. Cement Requirement: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" , for up to 7,500 feet of depth, mixed at 14.3 lbs./gal. with 6.3 gallons of fresh water per sack or class "H" , for deeper than 7,500 feet plugs, mixed at 16.4 lbs./gal. with 4.3 gallons of fresh water per sack.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).

7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-S to BLM. The report should give in detail the manner in which the plugging

work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.

Following the submittal and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.