			ENT OF THE	URVEY			06407		<u>.</u>
	SUND	RY NOT	CES AND RE	PORTS ON	I WELLS	6. 1	F INDIAN, AL	LOTTEE	OR TRIBE N.
					to a different reservoir.			7	
1.						7. 1	UNIT AGREEM	ENT NA	MB
OIL		OTHER	<u></u>				FARM OR LEA	GE NAM	
2. NAM	E OF OPERATOR	. P. Ya	tes	1	i9 33		lobinso		
8. ADDE	RESS OF OPERATOR					9. 1	WELL NO.		•
	309 Carp	er Buil	ding, Artes	sia, New	Mexieo		1-B		WILDCAT
 A. LOCATION OF WELL (Report location clearly and in accordance with any State requirements." See also space 17 below.) At surface 							Grayburg-Jackson		
	2310 FN	د ه 231	O FWL, NWX	SE			SEC., T., R., I SURVEY O	M., OR B	LE. AND
						34	-17S-2		÷.
14. PER!	MIT NO.		15. ELEVATIONS (Sh	ow whether DF, RT,	gr, etc.)		COUNTY OB		
						E	lddy		N-M
16.	i	Check An	propriate Box To	Indicate Nati	ure of Notice, Report, a	or Other	Data		
	NO	LICE OF INTEN	•				REPORT OF:	· ·	
TES	ST WATER SHUT-OFF	ı	PULL OR ALTER CASING	6 🗌 💧	WATER SHUT-OFF		REPA	IRING W	TELL
FR.	ACTURE TREAT		ULTIPLE COMPLETE		FRACTURE TREATMENT			RING CA	· · · · ·
	OOT OR ACIDIZE		BANDON*		SHOOTING OR ACIDIZING		ABAN	DONMEN	TT
	PAIR WELL		HANGE PLANS		(Other) (Note: Report rea Completion or Rec	sults of m	ultiple comp	letion	on Well
p	Plan to this work.)* Plan to to to the second	reat w is 3207 reat wi	ell throug '. Treat	h 7" casi formation	ing set at 304 from 3041' t ease oil and 5	1'. 0 309	Total 90' in	dep ope	th
p	roposed work. If w ent to this work.)* Plan to of hole : hole. T	reat w is 3207 reat wi	ell throug '. Treat	h 7" casi formation allons le	ing set at 304 from 3041' t	1'. 0 309	Total 90' in	dep ope	th
ם שני י	roposed work. If w ent to this work.)* Plan to of hole hole. T: frac sand	treat w is 3207 reat wi d.	ell throug '. Treat th 19000 g	h 7" casi formation allons le	and measured and true ve ing set at 304 h from 3041' t ease oil and 5	1'. 000 1	Total Total 90' in \$ of 20 1 and 1 and		th

.