

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

**WF P4 REG NP IRA MD MONH
MB AL JG SG KJ JS EMc VW LAND
DH BLM OCD RRCM RRCA CC BL BD**

| |
|--|
| WELL API NO. 30 015 03792 |
| Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| State Oil & Gas Lease No. B-4458 |
| Lease Name or Unit Agreement Name STATE B - 4458 |
| Well No. 2 |
| Pool name or Wildcat GRAYBURG JACKSON |

| | |
|---|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | |
| Name of Operator SOUTHWEST ROYALTIE, INC. | |
| Address of Operator P. O. BOX 11390; MIDLAND, TX 79702 | |
| Well Location Unit Letter <u>C</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line 36 Section 17S Township 29E Range NMPM EDDY County | |
| Elevation (Show whether DF, RKB, RT, GR, etc.) 3525 GR | |

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-18-01 RU TRIPLE N SERVICES.


4-19-01 RU WL. TIH & SET CIBP @ 3259'. RD WL. TIH W/TBG & SPOTTED 50 SX CMT ON CIBP. PU & SDFN.

4-20-01 TIH & TAG CMT @ 3,072'. LOADED CSG W/MUD. TOH W/TBG. RU WL. PERFED CSG @ 1,750'. UNABLE TO PMP IN. CONTACTED JERRY GUYE W/MOCD. RECEIVED PERMISSION TO SPOT 60 SX CMT PLUG INSIDE CSG.

4-23-01 TIH & TAGGED CMT PLUG @ 1,425'. RU WL. PERFED CSG @ 1,000'. RD WL. TIH & SQZ'D W/100 SX CMT. PU. SD & WOC 3 HRS. TIH & TAG CMT @ 862'. RU WL. PERFED CSG @ 550'. PMPD 60 SX CMT. PU. SD & WOC 3 HRS. TIH & DID NOT TAG PLUG. RU & PMP 2ND 60 SX CMT PLUG. SDFN & WOC.

4-24-01 TIH & TAG PLUG @ 182'. RU WL & PERED @ 150'. SQZ'ED W/100 SX CMT. PU SD & WOC 3 HRS. TIH & TAGGED PLUG @ 40'. FILLED CSG FR/40' TO SURFACE W/8 SX CMT. RD TRIPLE N SERVICES.

NOTE: ALL DOWNHOLE WORK COMPLETE. SURFACE RESTORATION HAS NOT BEEN STARTED.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE AREA SUPERVISOR-ENGINEER DATE 04-03-01
TYPE OR PRINT NAME C. M. BLOODWORTH TELEPHONE NO. 915 686-9927

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

