

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WF P4 REG NP IRA MD MONH
MB AL JG SG KJ JS EMc VW LAND
DH BLM OCD RRCM RRCA CC BL BD

WELL API NO. 30 015 03792
Indicate Type of Lease STATE ☒ FEE ☐
State Oil & Gas Lease No. B-4458
Lease Name or Unit Agreement Name STATE B - 4458
Well No. 2
Pool name or Wildcat GRAYBURG JACKSON

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
Name of Operator SOUTHWEST ROYALTIE, INC.	
Address of Operator P. O. BOX 11390; MIDLAND, TX 79702	
Well Location Unit Letter <u>C</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line 36 Section 17S Township 29E Range NMPM EDDY County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3525 GR	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-18-01 RU TRIPLE N SERVICES.

4-19-01 RU WL. TIH & SET CIBP @ 3259'. RD WL. TIH W/TBG & SPOTTED 50 SX CMT ON CIBP. PU & SDFN.

4-20-01 TIH & TAG CMT @ 3,072'. LOADED CSG W/MUD. TOH W/TBG. RU WL. PERFED CSG @ 1,750'. UNABLE TO PMP IN. CONTACTED JERRY GUYE W/NMOC. RECEIVED PERMISSION TO SPOT 60 SX CMT PLUG INSIDE CSG.

4-23-01 TIH & TAGGED CMT PLUG @ 1,425'. RU WL. PERFED CSG @ 1,000'. RD WL. TIH & SQZ'D W/100 SX CMT. PU. SD & WOC 3 HRS. TIH & TAG CMT @ 862'. RU WL. PERFED CSG @ 550'. PMPD 60 SX CMT. PU. SD & WOC 3 HRS. TIH & DID NOT TAG PLUG. RU & PMP 2ND 60 SX CMT PLUG. SDFN & WOC.

4-24-01 TIH & TAG PLUG @ 182'. RU WL & PERED @ 150'. SQZ'ED W/100 SX CMT. PU SD & WOC 3 HRS. TIH & TAGGED PLUG @ 40'. FILLED CSG FR/40' TO SURFACE W/8 SX CMT. RD TRIPLE N SERVICES.

NOTE: ALL DOWNHOLE WORK COMPLETE. SURFACE RESTORATION HAS NOT BEEN STARTED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE AREA SUPERVISOR-ENGINEER DATE 04-03-01
TYPE OR PRINT NAME C. M. BLOODWORTH TELEPHONE NO. 915 686-9927

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE OCT 30 2002

CONDITIONS OF APPROVAL, IF ANY:

4
MAY 2001
RECEIVED
Hobbs
OCD