

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

RECEIVED
 NEW MEXICO OIL CONSERVATION COMMISSION
 JUL 15 1968
O. C. C.
ARTESIA. OFFICE

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. B-1778	
7. Unit Agreement Name LOCO HILLS	
8. Farm or Lease Name State "A"	
9. Well No. NO. 2	
10. Field and Pool, or Wildcat LOCO HILLS GRAYBURG	
12. County Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator NEWMONT OIL COMPANY
3. Address of Operator P. O. BOX 1305, ARTESIA, NEW MEXICO
4. Location of Well UNIT LETTER 0 725 FEET FROM THE South LINE AND 2100 FEET FROM THE EAST LINE, SECTION 36 TOWNSHIP 17S RANGE 29E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3537' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>
		Plug & Abandon Well	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-19-68 to 6-6-68:

Set Baker C.I. Bridge Plug at 2696'. Set 25 sack plug at 2696'. Shot pipe at 1800'. Set 25 sack plug at 1800'. Shot pipe at 1608', 1522', 1308', 1201', 1110, 1015, and 916'. Set 25 sack plug at 1030'. Shot pipe at 761', 606' and 582'. Pulled 582' of 4 1/2" casing. Set Baker Cast Iron Bridge Plug in 8 5/8" casing at 430'. Set 25 sack plug at 430'. Shot 8 5/8" casing at 313' and 252'. Pulled 252' of 8 5/8" casing. Set regulation marker with 10 sacks cement. Cleaned location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>James L. Lidduth</i>	TITLE Division Superintendent	DATE 7-11-68
APPROVED BY <i>A. P. Stam</i>	TITLE SEAL AND GAS INSPECTOR	DATE AUG 27 1968

CONDITIONS OF APPROVAL, IF ANY: