

7-8-77

as per Tubb Log, the stick @ 2700 cut + pulled.
tested over & on the water flow of 2570 BPD.
went down to TD now 2057 BPD to run bit to bottom.
let water flow decrease log. set 4 1/2" just above
shot hole + cement.

8-10-77 F 1714 BPD

8-11-77 F 1714 BPD

8-12- F 1625 "

8-13 F 1285

11/200 BPD
2700

8-14 F 1582

8-15- F 1714 BPD

run logs. LK + Soligen

8-16-77 F 1878 BPD sample to 2695 + tested reg to
1000' OK. lowered to 2735, then would not hard, pulled.

8-17- F 1714 BPD.

8-19- F 1714 BPD

10.8-77
27100

7-20-77 run pkr to 2736 WF 400 LFD reset pkr @

2745 water flow shut off. reset pkr @ 2716 WF 1645 BPD

8-21-77 F 1582 BPD

