	SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
NEW M NAT	Attach this card to the back of the mailpiece, or on the front if space permits.	A. Signature X Junk Mthy Agent B. Received by (Printed Name) C. Date of Deliv C. Date of Deliv C. Date of Deliv
GARY E. JOHNSON Governor Betty Rivera Cabinet Secretary	^{1.} Article Addressed to: G P II ENERGY, INC. PO BOX 50682 MIDLAND TX 79710	D. Is delivery address different from item 1? / Yes If YES, enter delivery address below: INO
8 August 2002		Service Type Certified Mail Registered Insured Mail C.O.D.
Via Certified Mail	2. Article Number	4. Restricted Delivery? (Extra Fee)
G P II Energy, Inc.	(Transfer from service lat , 7001, 1940, 0001	9971 3372
P.O. Box 50682 Midland, Texas 79710	PS Form 3811, August 2001 Domestic Retur	In Receipt 102595-01-M-250
RE: NOTICE OF VIOLAT G P II Energy, Inc. Burnham Gray Featherstone # Federal KK # 1 Federal Q # 1	#2- burg SA Ut #3 H-2-17-30 API# 30-015-040 5 C-2-17-31 API# 30-015-050	058 034 015

Dear Sirs:

This letter shall serve as a Notice of Violation of the rules of the New Mexico Oil Conservation

All of these wells failed a MIT in February 2000 and G P II Energy, Inc. was notified verbally at the Inc. was by letters dated 4 -5-2002, 5-31-2002, and 6-4-2002 notified about this matter. This certific part because all directives have brought no response. The OCD is in receipt of C-103 forms dated \vdots indicating work will be done "when rig becomes available". Inspections in July and August found n

Rule 19.15.9.703 of the New Mexico Oil Conservation Division provides as follows:

19.15.9.703 OPERATION AND MAINTENANCE

A. Injection wells shall be equipped, operated, monitored, and maintained to facilitate periodic testing and to assure continued mechanical integrity which will result in no significant leak tubular goods and packing materials used and no significant fluid movement through vertical channels adjacent to the well bore.

B. Injection project, including injection wells and producing wells and all related surface facilities shall be operated and maintained at all times in such a manner as will confine the injected fluids to the interval or intervals approved and prevent surface damage or pollution resulting from leaks, breaks, or spills.

C. Failure of any injection well, producing well, or surface facility, which failure may endanger underground sources of drinking water, shall be reported under the "Immediate Notification" procedure of Rule 116.

D. Injection well or producing well failures requiring casing repair or cementing are to be reported to the Division prior to commencement of workover operations.

E. Injection wells or projects which have exhibited failure to confine injected fluids to the

authorized injection zone or zones may be subject to restriction of injection volume and pressure, or shutin, until the failure has been identified and corrected.

[7-1-81...2-1-96; 19.15.9.703 NMAC - Rn, 19 NMAC 15.I.703, 11-30-00]