

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVED
OFFICE FOR NO.
OF COPIES REQUIRED
(Other instructions on reverse side)

BLM Roswell District
Modified Form No.
NND60-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

144P 2-5-1992

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		O. C. D. ARTESIA OFFICE	
2. NAME OF OPERATOR Marbob Energy Corporation ✓		3a. Area Code & Phone No. 505-748-3303	
3. ADDRESS OF OPERATOR P. O. Drawer 217, Artesia, NM 88210			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980 FNL 660 FEL Unit H			
14. PERMIT NO. 30-015-04063		15. ELEVATIONS (Show whether DF, RT, OR, etc.)	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		7. UNIT AGREEMENT NAME	
		8. FARM OR LEASE NAME Parke	
		9. WELL NO. 4	
		10. FIELD AND POOL, OR WILDCAT Square Lake Grbg SA	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 3-T17S-R30E	
		12. COUNTY OR PARISH Eddy	13. STATE NM

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 2/27/92 RU, pulled rods & tbq, RIH w/4 3/4" bit & workstring, tag @ 2808', RIH w/pkr & plug to find hole in csg, csg leaking from 220' to parted csg @ 90'.
- 2/28/92 Spot cmt plug from 2871-2760', perf csg from 1380 & 545', could not pmp into perfs @ 1380', spot cmt plug from 1430-1330', sqzd perfs 545 w/50 sx Class C w/4% CC, did not tag, sqzd w/50 sx Class C w/4% CC.
- 3/3/92 Tag cmt @ 480', latch on 5 1/2" csg, pulled 5 jts. csg. laying down.
- 3/4/92 RIH w/short overshot & 2 7/8" tbq, could not get over parted csg, RIH w/long overshot, no luck, RIH w/same overshot & trimmed off a little, no luck, cut notch some more & work overshot over csg, POH w/overshot & RIH w/overshot w/5 1/2" csg 15.5# to 134', RIH w/2 7/8" tbq to 320', spot 100 sx plug, lost circ, POH w/tbg & waited 1 hr., started pmpg cmt down csg w/100 sx Class C w/4% CC, circ cmt to surf, waited 30 minutes, RIH w/2 7/8" tbq, washed out cmt to 135'.
- 3/5/92 Started DO cmt, DO to 360', lost circ, POH w/tbg & started swabbing, swab dry.
- 3/6/92 Started drlg again w/no success, sqzd hole in csg w/50 sx Class C w/4% CC, waited 2 hrs, started DO cmt, DO to 500' w/full returns.
- 3/7/92 DO cmt, CO to top of liner, POH w/bit & collar, RIH w/3 1/8" bit & 2 3/8" tbq, started DO cmt.
- 3/9/92 DO cmt in liner, CO to PBTD.
- 3/10/92 RIH w/pkr & plug, spot ac in liner w/20% ac, acd perfs w/500 gals. 15% NE ac, RIH w/tbg & rods, put well back on pmp.

ROBERT CHASE RECEIVED VERBAL APPROVAL FROM
ADAM W/BLM TO PROCEED WITH WORK 2/27/92.

18. I hereby certify that the foregoing is true and correct

SIGNED Shonda Nelson

TITLE Production Clerk

DATE 3/20/92

(This space for Federal or State office use)

Ag

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side