

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-074937

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME <i>Indefinite Production Company</i> ✓		7. UNIT AGREEMENT NAME	
3. ADDRESS <i>Box 17, Ioco Hills, New Mexico 88255</i> ☐ O. C. C.		8. FARM OR LEASE NAME <i>Federal RR</i>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>T. 17-S, R. 30-E, Eddy County, New Mexico</i>		9. WELL NO. <i>2</i>	
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT <i>Square Lake</i>	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <i>3742 GL</i>		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>Sec 3, T-17-S, R-30-E</i>	
		12. COUNTY OR PARISH <i>Eddy</i>	
		13. STATE <i>N.M.</i>	

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cleaned well out to TD 3050', Ran GR-Acoustic log, set and cemented 5 1/2" liner from 3049' - 2781', perforated Metax zone 2910' - 2924' and premier zone 3012' - 3020'. Ran tubing with straddle packers, treated with 60,000 gallons gelled water and 50,000# sand. Pulled and removed packers, ran tubing and rods and returned well to production on December 22, 1972.

18. I hereby certify that the foregoing is true and correct


Original Signed By
SIGNED *D. R. Layton*TITLE *Area Supervisor*DATE *December 26, 1972*

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE



*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

