

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instructions
verse side)

TE
re

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

CLSF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ WIW


2. NAME OF OPERATOR
J Cleo Thompson & James Cleo Thompson JR.

3. ADDRESS OF OPERATOR
P.O. Box 6445, Odessa, Texas 79767

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
1980' FNL & 660' FEL Sec. 4

14. PERMIT NO.

15. ELEVATIONS (Show whether depth, RT, GR, etc.)
3715'



5. LEASE DESIGNATION AND SERIAL NO
LC 047200 NMO2425

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
West Square Lake Un Tr.

9. WELL NO.
#2

10. FIELD AND POOL, OR WILDCAT
Square Lake - G-3f

11. SEC., T., S., M., OR BLK. AND SURVEY OR AREA
Sec. 4 T17s R30e

12. COUNTY OR PARISH
Eddy

13. STATE
NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) Plug and abandon

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☒
(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

- (1) C.I.B.P. at 2720' w/35' cement on top. ✓
- (2) Perf. @ 2225' set C.R. @ 2200' pump 50 sx cement. Set 200' on top of C.R. (Queens and Seven rivers.) ✓
- (3) Perf. 1200' set C.R. at 1180' pump 25 sx.cmt, set 100' cmt. on top of C.R. (Base of salt) ✓
- (4) Perf. @ 450' (50' above salt) pump down 5 1/2" csg. circulate to surface. Leave 5 1/2 full. ✓
- (5) Cut csg. 3' below ground & set surface marker. ✓



Post ID 2
5-1-87
PYA

18. I hereby certify that the foregoing is true and correct

SIGNED

Amelia K. King

TITLE

Production Manager

DATE

4-29-86

(This space for Federal or State office use)

APPROVED BY

Orig. Sgd. David L. Mari

TITLE

AREA MANAGER

DATE

4-24-87

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side