

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DEC 11 '90

WELL API NO. 30-015-04092
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LC-028785(B)
7. Lease Name or Unit Agreement Name Square Lake 12 Unit
8. Well No. 100
9. Pool name or Wildcat Square Lake Grbg SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3681' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER WIW <input checked="" type="checkbox"/>	2. Name of Operator Marbob Energy Corporation
3. Address of Operator P. O. Drawer 217, Artesia, NM 82810	4. Well Location Unit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line Section 6 Township 17S Range 30E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/23/90 RU, pulled pkr & tbq.

10/24/90 RIH w/4 3/4" bit & 6 drl collars.

10/25/90 CO to 2780', jet open hole section.

10/26/90 CO to 2780', re-jet open hole.

10/27/90 CO to TD & found 3' fill, RU Houston Services, ran tracer survey, found wtr flow @ 2488±91'.

10/29/90 RIH w/scrapper to 2450', RIH w/pkr & tstd csg to 500#--held okay.

10/30/90 Spot cmt plug from 2641-2488' w/60 sx, pulled up to 2488' & circ 30 sx.

10/31/90 Tagged plug @ 2488', RIH w/SV rtnr, set @ 2294', sqd wtr flow w/200 sx, Welex ran cmt bond log & found top cmt @ 1860', perfed csg @ 1880', RIH w/pkr, pressured up on perms, unable to break down. CONT'D

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rhonda Nelson TITLE Production Clerk DATE 12/10/90
TYPE OR PRINT NAME Rhonda Nelson TELEPHONE NO. 748-3303

(This space for State Use)

APPROVED BY Rhonda Nelson TITLE Production Clerk DATE 12/10/90
CONDITIONS OF APPROVAL, IF ANY:

MARBOB ENERGY CORPORATION
SQUARE LAKE 12 UNIT #100
1980 FSL 660 FWL
SEC. 6-T17S-R30E
EDDY COUNTY

- 11/1/90 Perfed csg @ 1110', set SV rtnr @ 1071', sqd perfs @ 1110' w/200 sx, perfed csg @ 450', sqd perfs w/135 sx cmt, circ 45 sx to pit.
- 11/2/90 DO cmt, tstd perfs, would not hold, sqd perfs @ 450' w/500 gals. flowchk & 400 sx cmt.
- 11/3/90 DO cmt.
- 11/5/90 DO cmt, perfs tstd okay, drld out SV rtnr, tstd perfs @ 1110'--held okay.
- 11/6/90 DO cmt.
- 11/7/90 DO all cmt & CO to TD.
- 11/12/90 Jet open hole.
- 11/13/90 Jet open hole & clean out fill, laid down workstring, RIH w/Baker Ad-1 pkr & 2 3/8" plastic costed used tbq, circ hole w/pkr fluid. Tstd csg to 500#--held okay. Put well back on injection.