

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TI
(Other instruct
verse side)

ICATE*
on re

Budget Bureau No. 1004-0135
Expires August 31, 1985

45F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	RECEIVED BY APR -6 1987 O. C. D. ARTESIA OFFICE	5. LEASE DESIGNATION AND SERIAL NO. <u>LC07875E</u>
2. NAME OF OPERATOR <u>Gulf Oil Corp.</u>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <u>P. O. Box 670, Hobbs, NM 88240</u>		7. UNIT AGREEMENT NAME <u>Shiner</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) <u>At surface</u> <u>660' FSL + 660 FWH</u>		8. FARM OR LEASE NAME
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>3676' GL</u>	9. WELL NO. <u>103</u>
		10. FIELD AND POOL, OR WILDCAT <u>Shiner</u>
		11. SEC., T., R., M., OR BLR. AND SURVEY OR AREA <u>Sic 6-7775-R30E</u>
		12. COUNTY OR PARISH <u>Eddy</u>
		13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

2264'
PCG up the log CIPD 2226' cut down 2264' lost 60.24 cmt
@ 2247' log plug @ 1858' Circ. plug abandonment mud.
Ref Csg @ 1075-76' + 553.54' lost cmt hit @ 968' Rpd 30.24 cmt
cap w/ 35' cmt. lost cmt hit @ 499' Rpd 50.24 cmt, lost plug
489'-400' 120 cmt. Circ cmt to surf. lost dry hole marker.
Char = Char loc. P-A 2-10-85.

18. I hereby certify that the foregoing is true and correct

SIGNED

ROD Rite
Orig. Sgd. Line

TITLE

AREA ENGINEER

DATE

2-25-85

(This space for Federal or State office use)

APPROVED BY

TITLE

AREA ENGINEER

DATE

2-28-85

3-31-87

Post ID-2

3-8-85

P-A

*See Instructions on Reverse Side