

RECEIVED  
OCD-ARTESIA  
3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19

**SUNDRY NOTICES AND REPORTS ON WELLS**  
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator  
WEBB Oil Company

3a. Address  
P.O. Box 1124, Artesia, N.M.

3b. Phone No. (include area code)  
505-748-2081

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
Sec 6, Twp 17S, Rge 30E  
Unit letter F 1650' FNL, 1980' FWL

5. Lease Serial No.  
NM 7752

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.  
DREWERY FED #2

9. API Well No.  
30-015-04099

10. Field and Pool, or Exploratory Area  
SQUARE LAKE GB, S.A.

11. County or Parish, State  
EDDY, NEW MEXICO

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input checked="" type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

Return Well to Production

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleting horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Well has been Returned to Pump, AND Well is now producing

Aug 2, 2001

Accepted for record - NMOCD

ACCEPTED FOR RECORD  
MAR 13 2002  
ALEXIS C. SWOBODA  
PETROLEUM ENGINEER

RECEIVED  
MAR 7 PM 1 20  
BUREAU OF LAND MANAGEMENT  
1301 W. GRAND AVENUE  
ARTESIA, NM 87010

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)  
RODNEY D. WEBB

Title  
OWNER

Signature  
Rodney D Webb

Date  
3-4-02

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Office

Date