

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Petroleum Corporation of Texas

3. ADDRESS OF OPERATOR
P. O. Box 911 Breckenridge, TX 76024

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
440' FSL & 880' FWL, Section 14, Township 17-S, Range 30-E,
Unit Letter "M"

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3694' GL

RECEIVED

JAN 31 1980

O. C. D.

ARTESIA OFFICE

5. LEASE DESIGNATION AND SERIAL NO.
LC-055259

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Flint "B" Federal

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Grayburg Jackson

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
14, 17-S, 30-E, NMPM

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Gentlemen:

The above well was plugged and abandoned May 23, 1978 in the following manner:

1. Tag top of junk @ 2200'
2. Set retainer @ 2247'
3. Pump 192 sx. cement on top of retainer
4. Circulate hole with 10# mud
5. Perforate 2 holes @ 1180', base of salt section
6. Squeeze 55 sx. cement to give 100' plug, 1080'-1180', at salt base
7. 23 sx. cement plug inside pipe, 1180'-1043'
8. Perforate 2 holes @ 461'
9. Squeeze 60 sx. cement to give 100' plug from 461'-361', inside and outside casing
10. Set 5 sx. cement plug in top of casing w/required marker

There was no casing recovered.

RECEIVED

JUN 6 1978

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

DATE June 6 1978

JAN 29 1980

18. I hereby certify that the foregoing is true and correct

SIGNED Arthur Boice

TITLE Division Superintendent

(This space for Federal or State office use)

ACTING DISTRICT ENGINEER

APPROVED BY ALBERT R. STALL

TITLE

CONDITIONS OF APPROVAL, IF ANY: