Form 3160-5 (August 1999) UNITED STATES 13()
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT (S)
SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

Lease Serial No. NMO467930

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
1. Type of Well	Thousand Divers Abo	ndon 1020	21222324	8 Well N	ame and No.		
Oil Well Gas Well Other Plug & Abandon Name of Operator					Dale H. Parke A Tract 1 #7		
Premier Oil & Ga	s. Inc. /	12	1	9. API We		<u> </u>	
3a. Address 3b. Phone No. (include area code)					30-015-04160		
P. O. Box 1246 -	Artesia, NM 88			10. Field ar	nd Pool, or Exploratory An	ea	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					Grayburg Jackson-SR-Q-GB-SA		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 330' FSL & 1650' FEL of Section 15-T175-R30E(T) Unit 0, SWSE					11. County or Parish, State		
Unit O, SWSE			\$ ⁷ /				
•		<u> </u>		<u> </u>	Eddy Co., NM		
12. CHECK AI	PPROPRIATE BOX(ES)	TO INDICATE NAT	REOF NOTICE, R	EPORT, O	R OTHER DATA		
TYPE OF SUBMISSION	YPE OF ACTION	OF ACTION					
	☐ Acidize	Deepen	Production (Start	t/Resume)	☐ Water Shut-Off		
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	-	Well Integrity		
	Casing Repair	New Construction	Recomplete		Other		
Subsequent Report	Change Plans	Plug and Abandon	_	andon			
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Water Disposal				
down for night. 10-25-2002 - Fin hole with pluggi WOC. Shut well 10-26-28-2002 - cement from 3056 WOC. Shut well 10-29-2002 - RIF wireline. RIH a	pled up BOP. Ri rigged down wir ished RIH with 2 ng mud. Spotted in for night. RIH with tubing -2756'. POOH.	gged up wireli eline. Starte 2-3/8" workstri 50 sacks Clas - did not tag WOC 4 hours. I tagged cement casing at 116	ne. RIH with do in hole with any and tagged as C Neat ceme plug. Spotte RIH with tubit at 2670'. P	h 2-3/8 TD at ent from ed 50 sa eng - ce	" workstring. 3056'. Circul 3056-2756'. cks Class C Ne ment still sof h tubing. Rig	Shut lated POOH. eat ft. POOH	
cement from 1160)-1060'. WOC.	Shut well in fo	or night.				
14. I hereby certify that the forego		, CC	ONTINUED ON NE	XT PAGE	:	-	
Name (Printed/Typed) Rusty Kleżn			Title Agent for BCM & Associates				
//	1/1						
Signature Kustu	STeen	Date	November 11,	The state of the s			
The second secon		E FOR FEDERAL OR	STATE OFFICE US			<u> </u>	
Approved by ORIG. S	GD.) ALEXIS C. SWO	BODA 🥦	TROLEUM EN	GINEER	bate NOV 18	<u> 2002 </u>	
Conditions of approval, if any, ar certify that the applicant holds le	e attached. Approval of this r gal or equitable title to those	notice does not warrant or rights in the subject lease	Office				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

which would entitle the applicant to conduct operations thereon.

PREMIER OIL & GAS, INC.
Dale H. Parke A Tract 1 #7
Section 15-T17S-R30E
Eddy County, New Mexico

SUNDRY NOTICE CONTINUED:

10-30-2002 - POOH with packer and tubing. Rigged up wireline. RIH and tagged cement at 970'. POOH and rigged down wireline. RIH open ended to 965'. Pumped 16 bbls mud laden fluid. POOH with tubing. Rigged up wireline. RIH and perforated 7" casing at 600'. POOH and rigged down wireline. RIH with packer and tubing and set packer at 306'. Squeezed with 60 sacks Class C Neat cement from 600-400'. WOC 4 hours. Rigged up wireline. RIH - cement still soft. POOH and rigged down wireline. WOC. Shut well in for night.

10-31-2002 - POOH with packer and tubing. Rigged up wireline. RIH and tagged cement at 335'. POOH and rigged down wireline. Rigged down tubing equipment. Rigged up wireline. RIH and perforated 7" casing at 60'. POOH and rigged down wireline. Nippled down BOP and nippled up wellhead. Installed 7" swedge. Squeezed with 30 sacks Class C Neat cement. WOC 4 hours. Rigged up wireline. RIH - did not tag. POOH and rigged down wireline. Squeezed with 45 sacks Class C Neat cement. WOC. Shut well in for night.

11-1-2002 - Rigged up wireline. RIH - did not tag. POOH and rigged down wireline. Pumped 30 sacks Class C Neat cement down 7" and up through 8-5/8" casing. WOC 4 hours. Topped off with 5 sacks Class C Neat cement. Rigged down pulling unit. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 10-31-2002.

Rusty Klein

Agent for BCM & Associates

November 11, 2002