

July 17, 1961

Harlan Production Company
P. O. Box 355
Monahans, Texas

Recd Aug 3-1961

Re: Etx-State Well # 2, Sec.
16-17S-30E, Eddy County, N.M.

Dear Sir:

I am returning Form C-103 on the above-captioned well. Please give us the Status of this well at the present time. Our records show this well to have 1320 feet of 8 $\frac{1}{2}$ " and 2565 feet of 6 $\frac{1}{4}$ " pipe in the hole.

I assume all of this pipe has been pulled; if so, you will need 425 feet of surface pipe circulated to the surface, and instead of Cal Seal Plug you will need a 25-sack plug at bottom of the hole and another 25-sack plug at the base of the plugged back total depth.

Very truly yours,

OIL CONSERVATION COMMISSION

MLA/sa
Encl: Form C-103

M. L. Armstrong
Supervisor, District No. 2

July 17, 1961

Harlan Production Company
P. O. Box 355
Lawrence, Kansas

Re: Hts-State Well No. 2, Sec.
16-17S-30E, 24th County, Kan.

Dear Sir:

I am returning Form C-103 on the above-captioned well. Please advise me the status of this well at the present time. Our records show this well to have 1320 feet of 6" and 2 1/2" pipe in the hole. I assume all of this pipe has been pulled; if so, you will need 432 feet of surface pipe circled to the surface, and instead of 2 1/2" plug you will need a 2 1/2" plug at bottom of the hole and another 2 1/2" plug at the base of the plugged back total depth.

Very truly yours,

Oil Conservation Division

L. L. Armstrong
Superintendent, District No. 2

Enc: Form C-103
LAA/ea