

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FEB - 2 1994

JAN 31 1994

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

MARBOB ENERGY CORP.

3. Address and Telephone No.

P.O. Drawer 217, ARTESIA, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec. 19 T-17-S R-30-E 1980 FSL 660FWL Unit Letter L

5. Lease Designation and Serial No.
LC-028793A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

BURCH KEELY UNIT

8. Well Name and No.

BURCH KEELY UNIT #92

9. API Well No.

30-015-04194

10. Field and Pool, or Exploratory Area

GRBG Jackson SR Q GRBGSA

11. County or Parish, State

Eddy NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1/31/94

- (1) spot 75 sack cement plug @ 3068', W.O.C. Tag @ 2829'
- (2) load hole w/mud
- (3) spot 15 sack cement plug @ 2829' to bring cement up
- (4) perforate 7" casing @ 2675'
- (5) squeeze 75 sack cement plug @ 2675' perforations, W.O.C., Tag @ 2527'
- (6) perforate 7" casing @ 900'
- (7) Squeeze 75 sack cement @ 900' perforation, W.O.C., tag @ 768'
- (8) perforate 7" casing @ 368'
- (9) squeezed 30 sack cement between 10 3/4 & 12 1/2 casing
squeezed 50 sack cement between 10 3/4 & 7" casing
spotted 40 sack cement inside 7" to surface, W.O.C. Tag @ 170'
- (10) perforate 7" casing @ 50'
- (11) broke circulations from 50' perforation to surface w/50 sack cement, set P&A marker

Port 10-2
2-18-94
P&A

14. I hereby certify that the foregoing is true and correct

Signed Jim Hean

Title

Date 2/1/94

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date