

Form 3160-5
November 1983)
(formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0115
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		RECEIVED
2. NAME OF OPERATOR Phillips Petroleum Company		MAR - 3 1992
3. ADDRESS OF OPERATOR 4001 Penbrook Street, Odessa, Texas 79762		O. C. D. OFFICE
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit I, 2615' FSL & 1295' FEL		
14. PERMIT NO API No. 30-015-04209	15. ELEVATIONS (Show whether OF, RT, GL, etc.) 3630' GL	
		5. LEASE DESIGNATION AND SERIAL NO LC-028793-A
		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
		7. UNIT AGREEMENT NAME
		8. FARM OR LEASE NAME Burch AA Fed
		9. WELL NO. 25
		10. FIELD AND POOL, OR WILDCAT Grayburg-JA, Sr-Q-GB-SA
		11. SEC., T., R., M., OR BLK. AND SUBST OR AREA 19, 17-S, 30-E
		12. COUNTY OR PARISH Eddy
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PELL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANT ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDISING ☐

(Other) Set CIBP above Producing
Interval and TA Wellbore.

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

X

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

CORRECTED COPY

1-28-92 GIH with 2-3/8" workstring. Land at 2450. COOH.

1-29-92 GIH with 7" gauge ring to 2500', COOH. GIH with 7" CIBP and set at 2475' COOH. GIH with dump bailer and dump 7 sacks of cement, appx. 35' of cement in 7" casing. GIH with workstring and land at 2435. Load held and pressure casing to 520#, w/95 Bbls inhibited Fluid. Integrity test passed. Don Early with BLM witnessed casing integrity test. laydown workstring. Wellbore TA, Complete drop from report. Request permit to TA Well for a period of 1 year.

18. I hereby certify that the foregoing is true and correct

SIGNER

L.M. Sanders
L.M. Sanders

TITLE Supervisor Reg/Proration

DATE 3-2-92
(915) 368-1488

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

