

NEW MEXICO OIL CONSERVATION COMMISSION

MAR 27 1980

O. C. D.

ARTESIA, OFFICE

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. LC029342	
7. Unit Agreement Name	
8. Farm or Lease Name Brigham H	
9. Well No. 2	
10. Field and Pool, or Wildcat Loco Hills Abo-SWD	
12. County Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Disposal Well</u>
2. Name of Operator <u>Holly Energy Inc.</u>
3. Address of Operator <u>Box 726 Artesia, N.M.</u>
4. Location of Well UNIT LETTER <u>L</u> <u>1650'</u> FEET FROM THE <u>South</u> LINE AND <u>330'</u> FEET FROM THE <u>West</u> LINE, SECTION <u>21</u> TOWNSHIP <u>17S</u> RANGE <u>30E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <u>3633GR</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER <u>Run plastic coated tubing and packer</u>	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Run bit & scrapper to 6840' circulate hple with fresh water. Pull bit and scrapper put on 5 1/2" R-4 tension packer. Run plastic coated tubing to 6668', set packer, treat with 4000 gallons 15% DaD acid. Test casing to 500 PSI. Shut well in for 30 hours put on disposal. 3-20-80

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Robert Loyd TITLE Dist. Superintendent DATE 3-21-80
APPROVED BY Mike Walker TITLE OIL AND GAS INSPECTOR DATE MAR 28 1980
CONDITIONS OF APPROVAL, IF ANY: