Form 3160-5 (September 2001) UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT 26272829303 FORM APPROVED OMB No. 1004-0135 Expires January 31, 2004

5. Lease Serial No.

NM 0558581

If Indian, Allottee or Tribe Name

CISF

SUNDRY NOTICES AND REPORTS ON WELLS AUG 2002

Do not use this form for proposals to drill or to re-enter enabandoned well. Use Form 3160-3 (APD) for such proposals EIVED

CD - ARIES 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side

Lype or ou		~~49	10161	
Oil Well 🚨 Gas Well 🚨	Other			8. Well Name and No.
2. Name of Operator South wast Royalties Inc.				McIntyre G Fed. No
South Wast Koy	alties toc.	Tai bi vi c 1 1	7.7	9. API Well No. 30 - 0/5- 04243
3a. Address 3b. Phone No. (include area code)			area coae) . 4017	10. Field and Pool, or Exploratory Area
P.O. Box 11390 Mid 44 & Tx 79702 915-686-9927 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			GB Jackson TR Queen	
Unil B; 330 ALL & 2,310 FEL; Sec 21, TITS, R30E				11. County or Parish, State
				Eddy Co, NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
TYPE OF SUBMISSION	TYPE OF ACTION			
_	Acidize	Deepen Deepen	Production (Start	/Resume)
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	☐ Well Integrity
D Salarana Barra	Casing Repair	New Construction	Recomplete	Other
Subsequent Report	Change Plans	Plug and Abandon	☐ Temporarily Ab	andon
☐ Final Abandonment Notice	Convert to Injection	Plug Back	☐ Water Disposal	
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Objective: Return Thed well to production in Seven Rivers Zone. I MIRW WS. TIH W/ logg my tools. Run GR-GNL los for PBTD to TOC (est for 1990' to 1,100'). Pick perforations in Seven Rivers Zone (est to be for 1500'). Pick perforations in Seven Rivers Pay.				
Break down pen fs w/acid. Swab tst perfs. Additional stimulation will acid. APPROVED AUG 26 2002				
14. I hereby certify that the foregoin Name (Printed/Typed) [M. Blood wor Signature	ng is true and correct	Title /	-as Super-	LES BABYAK
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by	ned .	Т	itle	Date
Conditions of approval, if any, are certify that the applicant holds leg which would entitle the applicant to	al or equitable title to those rig	hen in the cubicot loons !	office	,