

N.M. Oil Cons. Division
811 S. 1st Street
Artesia, NM 88210-2834
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Mack Energy Corporation

3. Address and Telephone No.

P.O. Box 960, Artesia, NM 88211-0960 (505)748-1288

4. Location of Well (Footage, Sec., T. R., M. or Survey Description)

1980 FSL 1650 FWL Sec 21-T17S-R30E

5. Lease Designation and Serial No.

LC-029342-A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Woolley Federal #3

9. API Well No.

30-015-04251

10. Field and Pool, or Exploratory Area

Loco Hills Abo

11. County or Parish, State

Eddy, N.M.

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION


- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Mack Energy Corporation proposes to plug as follows:

- TAG CIBP @ 5715' and verify top of cement*
1. Set 100' cement plug (45sx) 3558-3458'. 50' below and above 8 5/8" Intermediate casing. *TAG*
 2. Set 100' cement plug (45sx) 510-410'. 50' below and above 13 3/8" surface casing.
 3. Set 10sx cement surface plug.
 4. Install dry hole marker cut off anchors and fill in pit.



**SEE ATTACHED FOR
CONDITIONS OF APPROVAL**

14. I hereby certify that the foregoing is true and correct

Signed

Alexis C. Swoboda

Title

Production Analyst

Date

8/18/00

(This space for Federal or State office use)

(ORIG. SGD.) ALEXIS C. SWOBODA

Title

PETROLEUM ENGINEER

Date

AUG 23 2000

Approved by

Conditions of approval, if any: