Mack Energy Corp ration Berry A Federal #2

After Before Spot 60' surface plug 8 5/8 casing set @ 532' w/50 sx Perforate 7" @555' top of salt and squeeze 40 sx cement Perforate 7" @ 1100' bottom of salt and squeeze 40 sx cement 7" casing set @ 2620' w/100sxSet 100' cement plug 50' above and below bottom of 7" casing. Open hole from

2620-34001

EGERÓ TEMSOS EMANTON E PO ÉMBROS

53.5 VARE 13 VM 6:08

BECEVED