

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

45P

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
Phillips Petroleum Company

3. ADDRESS OF OPERATOR
4001 Penbrook St., Odessa, Texas 79762

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
Unit H, 2310 FNL and 330 FEL

14. PERMIT NO.
30-015-04258

15. ELEVATIONS (Show whether \pm , \pm , \pm , etc.)
3680' DF, 3670.3' GR

5. LEASE DESIGNATION AND SERIAL NO.
LC-029020-E

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Parke E

9. WELL NO.
2

10. FIELD AND POOL, OR WILDCAT
Jackson Abo

11. SEC., T., R., OR BLK. AND
SURVEY OR AREA
Sec. 22, T-17-S, R-30-E

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

07-04 to 07-06-90

Move in & RU DDU. Safety mtg. ND wellhead & NU BOP. GIH w/bit & 5-1/2" csg scraper to TD. GIH w/5-1/2" cmt retainer to 6850'. Pump 25 sks Class C Neat. Circ. hole w/9.5 mud laden fluid. ND BOP & wellhead. GIH w/2-3/8" tbg to 2050' & spot 25 sks Class C 2% CaCl. Tag plug 1950'. POOH to 1500' and spot 50 sks Class C 2% CaCl. Tag plug 1400'. POOH to 550' and spot 35 sks Class C 2% CaCl. POOH to 50' and spot 10 sks plug to surface. Cut off wellhead & install dry hole marker & cut dead men. RD DDU. Witnessed by BLM, J. Amos 7-6-90. Job complete.

Post ID-2
8-17-90
PvA

RECEIVED
JUL 31 10 39 AM '90

18. I hereby certify that the foregoing is true and correct

SIGNED

L. M. Sanders
L. M. Sanders

TITLE Supv., Reg. & Pro.

DATE 7/27/90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

8-3-90

CONDITIONS OF APPROVAL, IF ANY:

Approval of the well bore.

Liability under bond is retained until

surface restoration is completed. *See Instructions on Reverse Side