

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved. *copy to 3 F*
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 028028-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

D. H. Parke "A" *21*

9. WELL NO.

6

10. FIELD AND POOL, OR WELDCAT

Grayburg-Jackson
O. C. - 3-A11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 22, T-17S, R-30E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Shenandoah Oil Corporation ✓

3. ADDRESS OF OPERATOR

1500 Commerce Bldg., Ft. Worth, Texas 76102

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit E - 1,650 FNL 330 FWL Sec. 22, T-17S, R-30E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3,657' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

(Other) Convert to Injection Well

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

T.D. - 3,442' Open Hole 2,940' - 3,442' - San Andres Formation.

1. Pull rods and tubing.
2. Clean out to total depth.
3. Run 4½" liner from 2,850' to total depth and cement in place.
4. Perforate Grayburg-Jackson Zone and Premier Zone in selected intervals.
5. Run 2 3/8" O.D. internally plastic coated tubing with necessary packers and bottom hole flow regulators to dually inject into Grayburg-Jackson and Premier Zones.
6. Hook up well head for injection.

Note: Work will be performed in accordance with New Mexico Oil Conservation
Commission Order No. R-4133 (Case No. 4521).

RECEIVED

JUL 13 1971

O. G. C.
ARTESIA OFFICERECEIVED
JUL 12 1971U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED W. L. BEEKMANTITLE Manager, SecondaryDATE July 8, 1971

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

APPROVED

JUL 12 1971

W. L. BEEKMAN

ARTESIA OFFICE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. All necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local area, or regional procedure and practices, either are shown below or will be issued by the local Federal and/or State office.

Item 4: If the State has not completed the State requirements, locations on Federal or Indian lands should be described in accordance with the Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals for abandonment of all and subsequent reports of abandonment should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by casing or otherwise; depths (top of bottom) and method of placement of cement plugs and mud or other material placed below, between and above plugs; amount, size and kind of plug; and method of closing top of well; and date well sealed. Conditioned for final inspection looking for approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1962-0-882229

U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

1. NAME OF OPERATOR
2. ADDRESS OF OPERATOR
3. LOCATION OF WELL (Section, Township, Range, and other data)
4. DATE OF OPERATION
5. TYPE OF OPERATION
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA
7. OPERATOR'S SIGNATURE
8. TITLE
9. APPROVED BY
10. SIGNED
11. I hereby certify that the foregoing is true and correct