o not userthis form for proposals to d	OR PERMIT—" for such p	ry to a different reservoir proposals  RECEIVED	6. If Indian, Allottee or Tribe Name 7. If Unit or CA, Agreement Designation
	T IN TRIPLICATE		
ype of Well  Oil Gas Well Well Other Temporar: ame of Operator	ily Abandoned	JUL 29. '94	8. Well Name and No.
Premier Oil & GAs, Incorpora	ted	a C D	Gissler "A" #3
ddress and Telephone No.	ueu .	O. C. D.  ARTESIA, OFFICE	<b>⊣</b>
P.O. Box 1246, Artesia, NM 88	3210 (5	ARTESIA, 0,110 505) 748–2093	30-015-04281 10. Field and Pool, or Exploratory Area
ocation of Well (Footage, Sec., T., R., M., or Survey l	Description)	103) 110 2033	Grayburg-Jackson SR,Q,GB
Jnit F: 1330' FNL & 2310' F	'nπ		11. County or Parish, State
Sec 23, T-17S R-30E	WL		
		·	Eddy County, NM
CHECK APPROPRIATE BOX	(s) TO INDICATE NAT	URE OF NOTICE, REPO	ORT, OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTIO	N
X Notice of Intent	Abandon	nent	Change of Plans
	Recomple		New Construction
Subsequent Report	Plugging		Non-Routine Fracturing
	Casing R	epair	Water Shut-Off
Final Abandonment Notice	Altering	Casing	Conversion to Injection
	Other _	Casing Integrity Te	Dispose Water   (Note: Report results of multiple completion on Well
			Completion or Recompletion Report and Log form.)
Describe Proposed or Completed Operations (Clearly state give subsurface locations and measured and true vert	tical depths for all markers and zones		
give subsurface locations and measured and true veri It is the intention of the op- the casing on the subject we necessary to: (1) restore the oil zones. For these reasons subject to satisfactory casing in time for a witness to be p	perator to comply well. We do not wish ne well to production we ask for approving test. We will n	to plug and abando on, or (2) test bel al to temporarily a otify the Bureau of	on. It may be nind casing abandon the well

. 4

## BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

## Temporary Abandonment of Wells on Federal Lands

## Conditions of Approval

According to 43 CFR 3162.3-4-c, " No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544; for wells in Lea County call (505) 393-3612.
- 2. A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

- 1. Submits a subsequent Sundry Notice requesting TA approval,
- 2. Attaches a clear copy or the original of the pressure test chart,
- 3. And attaches a detailed justification why the well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.