	SUNDRY NOTICES AND REPORTS ON WELLS	5. LEASE DESIGNATION AND SERIAL NO. LC 029338A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do :	not use this form for proposals to drill or to deepen or plug back to a different reservoi Use "APPLICATION FOR PERMIT—" for such proposals.)	r.
WELF 2	11 1// 30-013-04263	Grayburg Jackson (San Andre
J. NAME OF		8. FARM OR LEASE NAME Unit [NM 886
3. ADDRESS (Burnett Oil Co., Inc. JUN 12	9. WBLL NO.
4. LOCATION See also s At surfac	Of WELL (Report location clearly and in accordance with any State requirements. C. C. space 17 below.)	= = ====)
At surrac	Unit A, 660'FNL, 660' FWL, Sec. 23, T17S, R30	OFFICE Grayburg Jackson (7RVS-QN-
		11. SEC., T., E., M., OR BLK. AND GB-SA) SURVEY OR AREA
14. PERMIT N		23 -17S-30E
	10. Sizvarions (Show whether Dr. RT, GR. etc.)	12. COUNTY OR PARISH 13. STATE
	3675'G.L.	Eddy NM

On November 1, 1988, this producing well was shut in due to economics. We request approval to keep this well shut in until such time as economics permit us to resume profitable operations of the well.

Completion or Recompletion Report and Log form.)

17 DESCRIBE THE POSED OF COMPLETE OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work if well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent.

FRACTURE TREATMENT

ABANDONMENT*

(Note: Report results of multiple completion on Well (ompletion or Recompletion Report and Log form.)

PULL OR ALTER CASING MULTIPLE COMPLETE

ABANDON*

BANGE LUAN

TEST WATER SHUT-OFF

Shut Well In

SHOOT OR ACIDIZE

1184 -

It who wetter the ne foregoing is true and correct		
Tals space for Federal or State office use)	Production Superintendent	DATE 12/20/88
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	CERTS, 15 in the second second	DATE 6-12-89