

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN THE REVERSE SIDE
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-030570(b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Re-Entry - Water Injection	7. UNIT AGREEMENT NAME Grayburg-Jackson Unit
2. NAME OF OPERATOR Anadarko Production Company	8. FARM OR LEASE NAME Tract 13
3. ADDRESS OF OPERATOR P. O. Box 200, Artesia, New Mexico	9. WELL NO. 8
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL & 1980' FSL Sec. 25 S4 SW4 Sec. 25 T17-S R30-E	10. FIELD AND POOL, OR WILDCAT Grayburg-Jackson
14. PERMIT NO. R-2323	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA N.M.P.M. 25-17-30
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 1,552' GR	12. COUNTY OR PARISH Lddy
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☒
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
(Other) ☒ Convert To Water Inf.	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3-11-66 - Moved in cable tool rig and cleaned out old hole to 3,367'.
Ran 3,363' of 3 1/2" O.D. 9.60# J-55 snls tubing for casing and set at 3,363'. Cemented casing w/900 mx class C neat cement. Cement circulated to surface. Plug down 4:00 PM. 4-8-66. WOC
5-1-66 - Perforated with Abrasi Jet tool two holes per ft at 3,300', 3,306', 3,330', 3,334', 3,338'. Commenced water injection 5-12-66 via 3 1/2" casing into perforations 3,300' - 3,338'.

Note - A Gamma Ray-Neutron Log was run after 3 1/2" casing was set to determine productive zones.

RECEIVED

MAY 29 1967

U. S. G. O.
*FEDERAL OFFICERECEIVED
MAY 25 1967
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct.

SIGNED

Charles E. Haggard
Charles E. HaggardTITLE **Production Foreman**DATE **May 21, 1967**

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

MAY 26 1967
R. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.