: orm 3160-5 June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Artesia, NM 88210-2834xpires: March 31, 1993 Artesia, NM 88210-2834xpires: March 31, 1993 Artesia, NM 88210-2834xpires: March 31, 1993 DEPARTMENT OF THE INTERIOR

N.M. Oil Cons. Division 811 S. 1st Street

Budget Bureau No. 1004-0135

FORM APPROVED

LC-028992 (B)

SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE Grayburg Jackson 1. Type of Well 8. Well Name and No. X Oil Well Gas Well U Other -6A1 Name of Operator 9. API Well No Pendragon Energy Partners, Inc. (30-015-8 3 Address and Telephone No. 303) 10. Field and Pool, or Exploratory 621 17th St., Ste. 750, Denver, CO 80293 4 Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 330' FWL & 990' FSL Eddy, NM Sec. 26, T-17-S, R-30-E CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Change of Plans Notice of Intent Abandonment **New Construction** Recompletion Non-Routine Fracturing Plugging Back Water Shut-Off Casing Repair Conversion to Injection Altering Casing Final Abandonment Notice Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 2-09-01 Set CIBP @ 3150', cap CIBP w/ 35' cmt. 2-12-01 Mix mud & Circulate. 2-12-01 Perf 4 holes @ 1350', set pkr @ 1200', pressure up to 1000 PSI, held. Spot 25 sx cmt. @ 1400', tag plug @ 1150'. 2-12-01 Perf 4 holes @ 584', set pkr @ 300', pressure up to 1000 PSI, held. Spot 25 sx cmt. @ 634'. 2-13-01 Tag plug @ 344'. 2-13-01 Perf 4 holes @ 50', circ. 20 sx cmt. from 50' to Surface. Leave 4-1/2" csg. full of cmt. 2-13-01 Install dry hole marker. Approved as to plugging of the well bore. Liability under bond is retained until Post py f surface restoration is completed, 14. I hereby certify that the foregoing is true and correct Agent DETROLEUM ENGINEER

or representations as to any matter within its jurisdiction

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements

