

2197

SUNDRY NOTICES AND REPORT ON WELL ABANDONMENT
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

1. Type of Well <input type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other Injection well		5. Lease Serial No. LC-028992(A)
2. Name of Operator Pendragon Energy Partners, Inc. /		7. If Unit or CA/Agreement, Name and/or No. Greyburg-Jackson TR. 7A
3. Address of Operator 621 17th St., Suite 750, Denver CO, 80293		8. Well Name and No. Unit #7A3 #3
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) NE-SE Sec 26 T.17S., R30E., 1370' FEL, 1650' FNL.		9. API Well No. 30-000-0000
		10. Field and Pool, or Exploratory Area
		11. County or Parish, State Eddy


12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection).

Abandonment History:

March 7, 2001: Set CIBP @ 3,000' and spot 25 sxs cement on top.
: Perforate 7" casing @ 1,500' and pump 40 sxs cement thru tubing & packer.
March 8, 2001: Tag cement plug @ 1365'.
: Cut off 7" casing @ 553'. POH & lay down casing.
March 9: 2001: Spot 50 sxs plug @ 610'. Tag cement @ 418'.
: Spot 60 sxs plug @ 418' to surface w/ marker.



14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) John Luchetta	Title Agent
Signature <i>J. Luchetta</i>	Date April 16, 2001

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

