

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN THE MANNER
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-059376

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

Crayburg-Jackson Unit

8. FARM OR LEASE NAME

Tract 11

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Crayburg-Jackson

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

27-17-30

N.M.P.M.

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Anadarko Production Company

3. ADDRESS OF OPERATOR

P. O. Box 260, Artesia, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface1650' FWL & 110' FWL Sec. 27
NW 1/4 NW 1/4 Sec. 27 T17-S R30-B

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3,624' RT

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.) *

January 17, 1967 form 9-331 was filed requesting permission to set
bridge plug and temporarily abandon this well. This form was approved
and signed by Mr. R. L. Beekman January 20, 1967.

We have received a notice dated May 18, 1967 requesting form 9-331
"Notice of Intention to Plug Back and Temporarily Abandon" signed
by Mr. James A. Knauf. I am sure Mr. Knauf is referring to form
9-331 "Subsequent report of Plug Back and Temporarily Abandon",
which this report will serve as.

The tubing and rods were pulled from well. The Western Company
set a Baker 5 1/2" cast iron drillable bridge plug with wire line
inside the 5 1/2" casing at 2,950'. Well was left full of fluid
and put on temporarily abandon status.

Final Report

RECEIVED
MAY 25 1967

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

TITLE

Production Form
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

DATE

May 23, 1967

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

MAY 26 1967

R. L. BEEKMAN

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.