1. Type of Well

UNITED STATES DEPARTMENT OF THE INTERIORN.M. OIL CONS. DIVISION BUREAU OF LAND MANAGEMEN

811 S. 1st Street

SUNDRY NOTICES AND REPORTS ON WELLISSIA, Do not use this form for proposals to drill or to deepen or reentry to a different resen	MM	8821
Do not use this form for proposals to drill or to deepen or reentry to a different reserv	voir.	

LC-060529

Use "APPLICATION FOR PERMIT -- for such proposals. SUBMIT IN TRIPLICATE 7. If Unit or CA, Agreement Designation AROC (TEXAS) INC 8. Well Name and No. Beeson "F" Federal No. 9 PO BOX 702373 9. Well API No. TULSA OK 74170-2373

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

330' FSL & 2310' FWL, Unit N Section 29, T17S, R30E

30-015-04381

10. Field and Pool, or Exploratory Area Loco Hills QN-GB-SA

11. County or Parish, State

Eddy County, New Mexico

	000001120; 1110; 11002				
12.	CHECK APPRO	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			
	TYPE OF SUBMISSION		TYPE OF ACTION		
	Notice of Intent		Abandonment Recompletion	Change of Plans New Construction	
	X Subsequent Report	SUBJECT	Plugging Back	Non-Routine Fracturing	
	Final Abandonment Notice	SUBJECT TO LIKE APPROVA BY STATE	Casing Repair Altering Casing	Water Shut-Off X Conversion to Injection	
		BI o	Other	Dispose Water	
				(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give					

ACCEPTED FOR RECORD

09/06/00 POH w/rod string & installed BOP.

09/07/00 RIH w/6 1/2" mill tooth bit, 6 - 4 3/4" DC's, 2 7/8" tbg & tagged CIBP @ 2872'. Repaired 7" casing near surface. P 2 9 2000

09/08/00 Pushed plug down hole to 3076'. Drilled plug from 3076' to 3077'. Drilled new formation from 3077' to 3080'. Circulated well clean.

___ (ORIG. SGD.) GARY GOURLE

09/09/00 RIH w/6 1/8" button bit, 10 - 4 3/4" DC's, 2 7/8" tbg. Drilled new formation from 3082' to 3098'. Circulated well clean.

09/10 thru 09/14/00 Drilled new formation from 3098' to 3355' (TD). Circulated well clean.

09/15/00 RIH w/4 1/2" shoe, 1-shoe jnt (43.72') 1-float collar, 73 jts 4 1/2" 10.5# casing and set shoe @ 3315.56'. Rigged up Halliburton Services & cemented w/225 sx Halliburton Lite w/1/4# FloCele, 135 sx cement w/2% CC. Circulated 76 sx cement to pit.

Cont'd on back

Date 09/26/00

THIS SPACE FOR FEDERA

Thallia Marshall

- 09/18/00 Installed head & BOP. Rigged up Black Warrior Wireline. Ran a Compensated Neutron & cement bond log. Perforated 2792', 2812' 21', 22', 52', 83', 2900', 01', 13', 14', 23', 41', 70', 3036', 42', 46', 53', 55', 61', 69', 87', 3169', 70', 71', 3279', 87', 89', 91' (28 holes). RIH w/4 1/2" 10.5# tension pkr, 2 3/8" tbg to 3294'.
- 09/19/00 Rigged up Halliburton Services to acidize well. Spotted 5 bbls acid @ 3294'. Pulled pkr up to 2736' & set. Acidized perfs 2792' to 3292' w/2500 gals 15% NEFE acid w/65 ball sealers.
- 09/20/00 POH w/2 3/8" tbg & pkr. RIH w/4 1/2" 10.5# plastic coated AD-1 tension pkr & 87jts new 2 3/8" plastic coated (TK-70) tbg. Circulated pkr fluid down the annulus. Set pkr @ 2748'. Tested annulus to 340 psi and held for 30 min held good.

and the second second second