	N. M. O.	C. C. COPY	Carry 451
Form 9-331 (May 1963)	UN :D STATES DEPARTMENT OF THE INTER GEOLOGICAL SURVEY	SUBMIT IN TRIPL 'E*	Rudget Ruggen No. 49 D1494
<b>.</b>	ORY NOTICES AND REPORTS orm for proposals to drill or to deepen or plug Use "APPLICATION FOR PERMIT" for such p	back to a different reservoir.	6. IF INDSAN, ALLOTTER OR TRIBE NAME
OIL GAS WELL	OTHER	RECEIVE	7. UNIT AGREEMENT NAME
	e Production Company	JUL 1 1974	8. FARM OR LEASE NAME POLCEDAL N
3. ADDRESS OF OFERATOR	or 67. Ione 3411s. Herr V	Kerteen BROKS	9. WELL NO.
P. O. Box 67, Loce Hills, New Maxiem. 58255  4. LOCATION OF WELL (Report location clearly and in accordance with any State resulting ments.*			10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface 2310 FS & 21			Loco Ella-
2310' FS & EL Sec. 31, T 178, R 30%			11. SEC., T., E., E., OR BLK. AND SUBVEY-OR AREA
	unty, New Mexico		31-17-30
14. PERMIT NO.	15. ELEVATIONS (Show whether Di	F, RT, GR, etc.)	12. COUNTY, OR PARISH 13. STATE
16.	Check Appropriate Box To Indicate N	Nature of Notice, Report, or C	Other Data
			UENT REPORT OF
TEST WATER SHUT-OF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CABING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS (Other) (Note: Report results of multiple conspletion on Well		
(Other Gordon	Loco Mills & Recomplete	Completion or Recomp	letion Report and Log form.)
17. DESCRIBE PROPOSED OR proposed work. If nent to this work.) *	COMPLETED OPERATIONS (Clearly state all pertines well is directionally drilled, give subsurface locs	it details, and give pertinent dates, tions and measured and true vertice	including settimated date of starting and all depths for all markers and zones perd-
Rig up	pulling unit. Coment 3q	queeze Loco Hills	perforations 2810
and 282	3-41 with 300 sacks come	nt. Drill out ne	w cement to FBTD
of 2848	. Drill out old cement	t from 2848* to 07	D of 1320'. Ree
32 EG (0	and the state of t		

complete this well in open hole as a Frender producer by fracing the Premier Zume 3055'-70' with 30,000 gals gelled Kon water and 30,000 sand. Put well on production.

18. I hereby certify that the foregoing is true and correct Area Supervisor SIGNED (This space for Federal or State office use) APPROVED BY NETTONS OF APPROVAL, IF AN TITLE DATE \_\_\_

\*See Instructions on Reverse Side