

OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

Copy

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		

Artesia, New Mexico
PlaceJune 7, 1945
Date

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO.
Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____
 Aston & Fair Scheurich State Well No. 2 in the _____
 Company or Operator Lease
 NW NW SE of Sec. 32, T. 17S, R. 30E, N. M. P. M.,
 Loco Hills Field, Eddy County.

The dates of this work were as follows: June 7, 1945
 Notice of intention to do the work was (was not) submitted on Form C-102 on June 7, 1945
 and approval of the proposed plan was (was not) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED
 On June 7, 1945 well was plugged as follows: Using Halliburton Oil well Cementing Equipment, run tubing to total depth, 3160', and circulated 125 sacks of mud to the surface. Pull tubing up to 2924' and spot 15 sacks of cement from 2924' to approximately 2850' throughout the Loco Hills Pay Horizon. Pull tubing up to 1200' and spot 10 sacks plug at base of slat. Remove tubing from hole and screw 8" bull plug in top of 8" casing; leaving 506' of 8 5/8" casing in the hole.

Witnessed by _____ Name _____ Company _____ Title _____

Subscribed and sworn before me this _____ day of _____, 19 _____

Notary Public _____

I hereby swear or affirm that the information given above is true and correct.

Name _____

Position _____

Representing _____ Company or Operator _____

My commission expires _____ Address _____

Remarks: Bridges should be placed under each cement plug to hold cement in place.

Approved: 6-12-45

Name

Title