

Vate Ref
St BX #5
32-17-30 - M

8 1/4" c 550' - 50 sp
7" c 2730 - 100 sp
TD c 2858 open hole.

Run log to TD & fill open hole to 50' inside
of 7" & 7' log.

100' plug c ~~2435~~ ^{Queen} c 2435

100 c 5R 1790

100 c BOS 1240

100 c TOS also 8 1/4 shoe c 600

Perforate c 600 + cr.

10 sp c surface