Copy

NEW MEXICO OIL CONSERVATION COMMISSION

SANTA FE, NEW MEXICO

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained See additional instructions in the Rules and Regulations of the Commission.

Indicate natu					
NOTICE OF INTENTION TO TEST CASING SHUT-OFF	x	NOTICE OF INTE	NTION TO SHO TREAT WELI	OT OR	
NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTE	NTION TO PUL ALTER CASIN	L OR G	
NOTICE OF INTENTION TO REPAIR WELL		NOTICE OF INTE	NTION TO PLU	G WELL	
NOTICE OF INTENTION TO DEEPEN WELL					
	A	rtesia. New Mexi	loo .	August 1,	1947
OIL CONSERVATION COMMISSION, Santa Fe, New Mexico. Gentlemen: Following is a notice of intention to do certain w	vork as d	lescribed below at t	he		
Aston & Fair	Scheu	4: .	Well No	5B in	SW NW
Company or Operator of Sec. 32 , T. 178 , R308	ease	, N. M. P. M.,	Loco Hil	ls	Field
EddyCou	n tu				
rollow instructions in the nabout August 2, 1947 plan to run irectly on top of the salt and cemental Well Comenting equipment. After	RULES approzent sam waiti	simately 475° of ne with 30 samks ing 18 hours for	8-1/4" used of cement u	l lap weld sing Hall set, will	Tourco
	RULES approzent sam waiti	AND REGULATION simately 475° of ne with 30 samks ing 18 hours for	8-1/4" used of cement u	l lap weld sing Hall set, will	Tourco
n about August 2, 1947 plan to run irectly on top of the salt and ceme	approzent same waiti	and REGULATION imately 475° of me with 30 samks ing 48 hours for mg test to determine	8-1/4" used of cement u cement to s mine water s	l lap weld sing Hall set, will shut off.	Tourto
FOLLOW INSTRUCTIONS IN THE n about August 2, 1947 plan to run irectly on top of the salt and ceme il Well Cementing equipment. After lug, bail hole dry and make 4 hour Approved August 1	approzent same waiti	And REGULATION simately 475' of ne with 30 samks ing 48 hours for ng test to determ Ast ByChuk_Ast PositionGen Send com	8-1/4" used of cement u cement to smine water smine smine water sm	l lap weld sing Hall set, will shut off.	drill,
FOLLOW INSTRUCTIONS IN THE n about August 2, 1947 plan to run irectly on top of the salt and ceme il Well Cementing equipment. After lug, bail hole dry and make 4 hour Approved August 1	approzent same waiti	Ast Ast Position Gen Send com Name Chuck A	8-1/4" used of cement used of cement to smine water sm	l lap weld sing Hall set, will thut off.	drill,
n about August 2, 1947 plan to run irectly on top of the salt and cemed il Well Cementing equipment. After lug, bail hole dry and make 4 hour Approved August 1 except as follows:	approzent same waiti	Ast Ast Position Gen Send com Name Chuck A	8-1/4" used of cement u cement to smine water smine smine water sm	l lap weld sing Hall set, will thut off.	drill,