

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

U. S. M. O. C. C. COPY
SUBMIT IN TRIP
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	15. ELEVATIONS (Show whether DF, RT, GR, etc.)
2. NAME OF OPERATOR General American Oil Company of Texas	3581' DF
3. ADDRESS OF OPERATOR P. O. Box 416 Loco Hills, New Mexico 88255	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FML and 660' FWL Sec. 35, T-27S, R-30E	
14. PERMIT NO.	

5. LEASE DESIGNATION AND SERIAL NO. LC-060525
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME Grayburg-Jackson
9. WELL NO. 2
10. FIELD AND POOL, OR WILDCAT Grayburg-Jackson
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 35, T-27S, R-30E
12. COUNTY OR PARISH Eddy
13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	PULL OR ALTER CASING
FRACTURE TREAT	MULTIPLE COMPLETE
SHOOT OR ACIDIZE	ABANDON*
REPAIR WELL	CHANGE PLANS
(Other)	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREATMENT	ALTERING CASING
SHOOTING OR ACIDIZING	ABANDONMENT*
(Other)	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PROPOSED WORK: We propose to Plug and Abandon this well by setting a 50' cement plug from 3150'-3100'. We will attempt to salvage 5-1/2" casing from approximately 2200'. We will set 100' bridge plug 50' inside and 50' outside stub of 5-1/2" casing. We will set a 50' plug from 1400'- 1350' and 25 plug at surface. No surface water indicated. Regulation marker will be erected. Any Pits will be filled and the location will be leveled and cleared of any junk.

RECEIVED

APR 29 1975 APR 30 1975

U. S. GEOLOGICAL SURVEY O. C. C.
ALBUQUERQUE, NEW MEXICO ALBUQUERQUE, OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED Roy Crow TITLE District Superintendent DATE April 24, 1975

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE Subject to 100' instead of 50' DATE 4/25/75
Cement plugs as indicated above.

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.