. **-	
	to tanks or gas to pipe line: Jarmary 25, 1952
	11 or gas: TEXAS-NEW MEXICO PIPE LINE COMPANY
Remarks:	er rell
	Sinclair Oil & Gas Gempany Company or Operator
	By: 103 Bhus
	Position: Dist. Supt
Send communication	is regarding well to:
	Name: Sinclair Oil & Gas Company
	Address: P. O. Box 1927
	Hobbs, New Mexico
APPR	OVED
OIL	CONSERVATION COMMISSION
By:	L. a. Janson
Title	: Dil trop per manganap

OIL CONSERVATION COMMISSIC.4 Santa Fe, New Mexico

REQUEST FOR (OIL)-(GAS) ALLOWABLE

It is necessary that this form be submitted by the operator before an initial allowable will be assigned to any completed oil or gas well. Form C-110 (Certificate of Compliance and Authorization to Transport 0il) will not be approved until Form C-104 is filed with the Commission. Form C-104 is to be submitted in triplicate to the office to which Form C-101 was sent. Two copies will be retained there and the other submitted to the Proration Office, Hobbs, New Mexico. The allowable will be assigned effective 7:00 a.m. on date of completion, provided completion report is filed during month of completion. The completion date shall be that date in the case of an oil well when oil is delivered into the stock tanks. Gas must be reported on 15.025 P.B. at 60° Eahrenheit

Hebbs, New Mexico Place				Jamary 25, 1952 Date		
			ace			
WE ARE HE	EREBY REC	QUESTING	AN ALLOWABLE FOR A WELL KNOWN A	AS:		
C	ompany o	or Opera	pany J. L. Koel "B" Well No	in 1/	41/4	
	•					
section	,	T. L [3,	R. 31E ,N.M.P.MOrayburg-Jo	acksop ₀₀₁	County	
'lease in	dicate 1	ocation	Elevation 3845 Spudded	11-10-51 Complete	d 1-25-52	
						
			Total Depth 3497			
			Top 0il/Gas Pay 3995 T Initial Production Test: Pump	op Water Pay		
			Initial Production Test: Pump	FlowFlow	BOPD OR CU.F GAS PER DA	
		1	Based on Bbls. Oil in	Hrs	Mins	
		 	Method of Test (Pitot, gauge,	prover, meter ru	n):	
			Size of choke in inches			
			Tubing (Size)		3090 Feet	
			Pressures: Tubing			
	0		Gas/Oil Ratio	Gravity 36		
			Casing Pe	rforations:		
nit let	ter: 0		Nom)		
			Acid Record:	Show of Oil, Ga	as and water	
sing & (Cementin	g Record	Gals to			
Size	Feet	Sax	Gals to	S/		
1			Gals to	S/		
5/8"	609	100	Shooting Record.	S/		
			60 Qts 3090 to 3120	_ <u>S/</u>		
7"	2992	200		0/		
7/0=	2000		Qts to	_ s/		
2 1/2"	3090		Natural Production Test: 24		ab Flowing	
			Test after acid or shot: 47	444444		
		'				
ease inc	dicate be	elow Form	mation Tops (in conformance with	geographical sect	ion of state)	
			ern New Mexico			
A 1				Northwestern Ne	w Mexico	
Anny	T. Devonian					
Sart	T. Silurian			T. Kirtland-Fruitland		

T. Montoya _____ T. Farmington____

T. McKee _____ T. Cliff House ____

T. Ellenburger _____

T. Simpson _____ T. Pictured Cliffs____

T. Wenefee

B. Salt _____

T. Yates ____

T. 7 Rivers

T. Queen_