L CONSERVATION COMMISSION Santa Fe, New Mexico®



July 17, 1951

REQUEST FOR (OIL)-(GAS) ALLOWABLE

It is necessary that this form be submitted by the operator before an initial allowable will be assigned to any completed oil or gas well. Form C-110 (Certificate of Compliance and Authorization to Transport Oil) will not be approved until Form C-104 is filed with the Commission. Form C-104 is to be submitted in triplicate to the office to which Form C-101 was sent. Two copies will be retained there and the other submitted to the Proration Office, Hobbs, New Mexico. The allowable will be assigned effective 7:00 a.m. on date of completion, provided completion report is filed during month of completion. The completion date shall be that date in the case of an oil well when oil is delivered into the stock tanks. Gas must be reported on 15.025 P.B. at 60° Fahrenheit.

Hobbs, New Mexico

T. Miss ___

		Plac	e .	•	Date	
WE ARE HE	REBY REQ	UESTING A	N ALLOWABLE FOR A W	ELL KNOWN AS:		
Sinelair	011 & G	as Company	y J. L. Keel r Lease	"B" Well No.	in SW 1/2	1 KB 1/4
C	ompany o	г Operato	r Lease	Ville	~	
acation	8	т 17 S	R. 318 .N.M.P.	Graviture Jeck	MPno1 Kd	dv County
section	· · ·	1	× 4 4 6 10 6 1 6 10			·
Please in	ndicate 1	ocation:	Elevation 3788	Spudded_ K	y 29,51 Completed	July 17, 1951
			Total Depth 3080	P.B	•	
			Top Oil/Gas Pay 36 Initial Production	067 Top	Water Pay	(BORD OB CL. ET)
		;	Initial Production	Test: Pump	Flow	GAS PER DAY
	o		Based on 65 Bbl	s. 0il in	llrs	Mins.
			Method of Test (Pi	tot, gauge, p	rover, meter ru	n):
			Size of choke in i	nches		
			Tubing (Size) 2*	UE	@	3050 Feet
		-	Pressures: Tubing			
			Gas/Oil Ratio			
			Gas/UII Ratio	Casing Perf		
						
Unit let	ter: <u>G</u>					
			Acid Record:		Show of Oil.Ga	
Casing &	Cementin	g Record	Gals			
Size	Feet	Sax	Gals			
		3.00		10	S/	
10 3/4	596	100	Shooting Record. 60 Qts 305	n to 2000		
7×	2945	200	Qts		S/	
	1, 40		Qts		S/	
			4.55		S/	
			Natural Production	Test: 30	Sab ing	Flowing
			Test after acid or	shot: xiix	Pumping	66 Flowing
l	<u> </u>		1000 area mara o.			
Please in	ndicate b	elow Form	ation Tops (in confo	rmance with g	eographical sec	tion of state):
	s	outheaste	ern New Mexico		Northwestern N	ew Mexico
T. Anhv	Tansil	1420	T. Devonian	Т	. Ojo Alamo	
		,		Т	. Kirtland-Frui	tland
B. Salt			T. Montoya		. Farmington	
					. Pictured Clif	
T. 7 Rive			T. McKee		Cliff House	
		2535			Menefee	
		2936	T. Gr. Wash		Point Lookout	
					. Mancos . Dakota	
					. Morrison	
					· Penn	
			_		1	

T.

	as: TEXAS-NEW MEXICO PIPE LINE COMPANY		
Remarks:			
Hemai RS.			
,	Sinclain Oil & Gea Comp. w		
	Company or Operator		
	By: 11. B. Rhees		
	Signatur		
	Position: Dist. Sapt.		
Send communications regar	ding well to:		
	Name: Sinelair Oil & Gas Co.		
	Address: Box 1427 Hebbs, N.M.		
APPROVED	, 1 <u>9</u> <u> </u>		
	ERVATION COMMISSION		
By:	At Harra		
	AND GAS INSPECTOR		
/ / /	THE ONE THOPECTOR		

Orig: & ee: OCC 2-ee USGS ee; WHC RAW F