

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN T
(Other instruc
reverse side)

Form approved
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. Las Cruces 055229	
2. NAME OF OPERATOR Sinclair Oil & Gas Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 1720, Hobbs, New Mexico		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 560' from North line and 1980' from East line		8. FARM OR LEASE NAME J. L. Keel "B"	
14. PERMIT NO.		9. WELL NO. 10	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3812' GR		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 8-7179-R31E	
		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☒	ABANDONMENT* ☐
(Other) Deepening	☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4-28-65 to Move in rig up cable tools. Cleanout to 3127' and deepen to 3413'.
5-18-65
5-24-65 Treated Lovington open hole selectively w/500 gals. M.A. from 3340-3413',
Vacuum from 3280-3340' w/500 gals. spearhead acid and Premier from 3195-
3255' w/500 gals. M.A. Max. Press. 3000#, Min. Press. 1200# @ 1.8 B'W.
5-30-65 On 24 hr. potential test ending 6:00 AM 5-31-65 pumped Grayburg open hole
3019-3413' 132 BWO, Gvty 34.6 plus 10 BFW on 2" pump w/10 - 86" strokes
per. min. GOR 240:1.

RECEIVED

JUN 7 1965

O. C. C.
ARTESIA, OFFICE

RECEIVED
JUN 3 1965
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Superintendent

DATE

6-2-65

(This space for Federal or State office use)

APPROVED BY


CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

Orig & 2cc: USGS Artesia,
cc: Regional Office Ar. H. H.
cc: file

*See Instructions on Reverse Side



Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.