SUNDRY N (Do not use this form for p Use "APF	OTICES AND R		WELLS		N, ALLOTTEE OR	# "AAL
Use "API	LICATION FOR PERMI			7. UNIT A0	REEMENT NAME	
OIL CAS WELL OTH	r WIW					
Hondo Oil & Gas Com	Dany A	۱۵	JG 28 '89		LEASE NAME	
ADDRESS OF OPERATOR				9. WBLL NO	. West "B" o.	
P. O. Box 2208, Ros	well, NM 88202	ance with any Shed	C. C. D.	17	AND POOL, OR WI	
See also space 17 below.) At surface					ourg Jacks	
1980' FSL & 660' FE	L			11. SEC., T.	. R., M., OR BLK BY OB ARMA	AND
· · · · · · · · · · · · · · · · · · ·			•	Sec. 9	9-T17S-R31	Е
PERMIT NO.	15. ELEVATIONS (S	Show whether DF, RT,			OR PARISH 13.	
		3889' GR		Eddy		NM
		o Indicate Natu	re of Notice, Report, o			
	NTENTION TO:			SEQUENT EBPORT	0 F :	<u> </u>
TEST WATER SHUT-OFF	PULL OR ALTER CASE MULTIPLE COMPLETE		WATER SHUT-OFF FRACTURE TREATMENT		REPAIRING WELL	
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZING	Y	LTERING CASING	
REPAIR WELL	CHANGE PLANS		(Other) deepened	=		X
(Other) DESCRIGE PROPOSED OR COMPLETED proposed work. If well is dia nent to this work.) *	OPERATIONS (Clearly sta rectionally drilled, give a	nte all pertinent det subsurface locations	(NOTE: Report rest Completion or Reco alls, and give pertinent da and measured and true ver		imated date of a all markers and	starting any zones perti-
DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dir	Drilled and deepened to Acidized OH	cleaned out new TD of 39 3670-3930' v	- * * * * * * *	tes, including est tical depths for 570' and " bit. 0% SXE	imated date of a all markers and co	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.