

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN
(Other insti
verse side)

PLICATE*
38 29 10

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

I - Sec - 276

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Shelly Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 730, Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FSL and 660' FWL Section 14-178-31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3897' DF

7. UNIT AGREEMENT NAME

Shelly Unit

8. FARM OR LEASE NAME

9. WELL NO.

24

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson

11. SEC. T., R., M., OR BLE. AND
SURVEY OR AREA

Section 14-178-31E

12. COUNTY OR PARISH

Hddy

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Perforate and Treat

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Well is presently producing through 5-1/2"OD casing perforations 3553-3760' (intervals)
in the Grayburg Formation.

We propose to perforate the Grayburg and San Andres and treat as follows:

1. Move in and rig up pulling unit.
2. Pull rods and tubing.
3. Perforate 5-1/2"OD casing from 3282' to 3821' in the Grayburg and San Andres Formations.
4. Run retrievable bridge plug.
5. Acidize through 5-1/2"OD casing perforations, 3799-3821' with 1,000 gallons acid.
6. Isolate and acidize through 5-1/2"OD casing perforations 3619-3861' with 1,000 gallons acid.
7. Isolate and acidize through 5-1/2"OD casing perforations 3282-3477' with 1,000 gallons acid.
8. Pull bridge plug.
9. Sand water frac through 5-1/2"OD casing perforations 3282-3477' with 15,000 gallons water and 15,000# sand.
10. Run tubing and rods and return well to a producing status.

18. I hereby certify that the foregoing is true and correct

SIGNED SIGNED V. E. Fletcher

TITLE District Superintendent

DATE March 15, 1967

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

APPROVED
MAR 20
R. L. BECKMAN
ACTING DISTRICT ENGINEER

RECEIVED
MAY 2 1967
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

APPROVED