NM OIL CONS. COMMISSION Drawer DD Artesia. NM 88210

.

- -

.

. Lines

1. 111.20

1

C/8/7

Form 9-331 Dec. 1973		RECEIVEL	D BY	7		Approve Bureau	d. 1 No. 42–R1	.424
UN	ITED STATES		5. LEAS			1		
DEPARTMEN	IT OF THE INTERIOF	R SEP 07 1	CanLC-0	9420	(b)	1		
GEOLO	DGICAL SURVEY		°€. IF IN	DIAN, AI	LLOTTEE	OR TRI	BE NAME	
SUNDRY NOTICES	AND REPORTS	NOVELS		AGREE	MENT NA	ME	· · ·	
(Do not use this form for proposals reservoir. Use Form 9-331-C for suc	ch proposalsi A	back to a different	8. FAR		ASE NAM	E		
1. oil gas well well	other N <u>G</u> √ ≤ 1	6 1982	9. WEL	L NO.				
2. NAME OF OPERATOR		• • • • •	- 7	6			1.11	
2. NAME OF OPERATOR CLASSES Getty Oil Company					LDCAT N	AME	4 1 2	
3. ADDRESS OF OPERATOR		001/12/20						
P.O. Box 730, Ho	bbs, NM 88240		_			LK. AN	D SURVE	Y OR
4. LOCATION OF WELL (REI	PORT LOCATION CLEARL	Y. See space 17	ARE.	A 21. '	17 I-215,	R-31	Е	
below.)	× 0 720 ₽ST & 1	980 FEL						
AT SURFACE: Unit Ltr. 0, 720 FSL & 1980 FEL					PARISH		NM	
AT TOP PROD. INTERVA AT TOTAL DEPTH:	L.		I	·····	<u> </u>			
	OV TO UNDIOATE NATU		_ 14. API	NO.				
16. CHECK APPROPRIATE B		RE OF NOTICE,						
REPORT, OR OTHER DA					•	DF, K	DB, AND	WD)
REQUEST FOR APPROVAL T	O: SUBSEQUENT	REPORT OF:	L	3806'	DF		· · · · · · · · · · · · · · · · · · ·	
TEST WATER SHUT-OFF						÷		
FRACTURE TREAT						<u>.</u>		
SHOOT OR ACIDIZE				-	2			
REPAIR WELL							mpletion or	zone
PULL OR ALTER CASING				change o	n Form 9–3	30.)	승규는 것	
MULTIPLE COMPLETE					11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	:2		
CHANGE ZONES								1
ABANDON*						T.		
(other)						-		•
17. DESCRIBE PROPOSED C including estimated date measured and true vertic	OR COMPLETED OPERATI of starting any proposed al depths for all markers	work. If well is	directionally	/ drilled.	ails, and give sub	give p surface	ertinent d locations	ates and
					·· `			
782 Rig up Penc	o. Pull rods & p	pump. Knox	treated	l circ	. hole	w/v	water,	spo
8/82 Rig up Peng bbls uniche	jo. Pull rods & j em descaleant acro	pump. Knox oss perfs a	treated t 2205-2	l circ 265 -	. hole 5 hol	w/v es.	water, Let se	

Rig up POH w/ rods & tbg. Ran bit & scrapper to 2355'. P.O.H. ran arrow 10/15/82 pkr & set @ 2101'. Knox acidized w/ 2500 gals 15% NE-FE acid & 15 ball sealers. Balled out at 4800#, max 4800#, min 1700#, ISIP 1500#, 15 min 1250, Avg rate 4.1 BPM. 78 load, 60 acid, 138 total flowed back.

Ran tbg, rods & pump started pumping. Rig down. Placed well back on 10/16/82 production. .

Subsurface Safety Valve: Manu. and Type	Set @ Ft.				
18. I hereby certify that the foregoing is true and correct SIGNED					
ACCEPTED FOR RECOND space for Federal or State office use)	· · · · · · · · · · · · · · · · · · ·				
APPROVED BY (ORIC SCD) DAVID R GLASS DATE CONDITIONS OF APPROVGED ANY 6 1983					
ROSWELL. NEW MEXICO •Sée Instructions on Reverse Side					