

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN THE MANNER  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

**LC-029418(B)**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

**Skelly Unit**

8. FARM OR LEASE NAME

**Skelly Unit**

9. WELL NO.

**70**

10. FIELD AND POOL, OR WILDCAT

**Grayburg-Jackson**11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA**Sec. 23-178-31E**

12. COUNTY OR PARISH

**Eddy**

13. STATE

**New Mexico**

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL ☒ GAS ☐  
WELL ☒ WELL ☐ OTHER

2. NAME OF OPERATOR

**Skelly Oil Company**

3. ADDRESS OF OPERATOR

**P. O. Box 1351, Midland, Texas 79701**4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface**1980' FSL & 660' FHL of Section 23-178-31E**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

**3881' DF**

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

**Clean out and treat**(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

- 1) Moved in pulling unit 8-23-73. Pulled rods and tubing.
- 2) Cleaned out inside of 4-1/2" OD liner to 3874' FBTD.
- 3) Spotted 750 gallons of 15% regular acid across perforations 3288-3866' and let acid soak 12 hours.
- 4) Ran tubing and rods.
- 5) Returned well to production 8-24-73, producing 25 barrels of oil and 27 barrels of water per day, through San Andres Perforations 3288-3866'.

18. I hereby certify that the foregoing is true and correct

SIGNED

**D. R. Crow**

TITLE

**Lead Clerk**


DATE

**Sept. 10, 1973**

(This space for Federal or State office use)

TITLE

DATE



\*See Instructions on Reverse Side

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.