

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St. NE  
Santa Fe, NM 87505

RECEIVED  
OCD - ARTESIA

WELL API NO.  
30-015-10542

Indicate Type of Lease  
STATE ☒ FEE ☐

State Oil & Gas Lease No.  
F-4201

Lease Name or Unit Agreement Name  
Continental "E" State

Well No.  
4

Pool name or Wildcat  
Artesia Queen Grayburg SA

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:  
OIL WELL ☐ GAS WELL ☐ OTHER

Name of Operator  
Mack Energy Corporation

Address of Operator  
P.O. Box 960, Artesia, NM 88211-0960

Well Location  
Unit Letter F : 2310 Feet From The North Line and 1911 Feet From The West Line  
30 Section 17S Township 29E Range NMPM Eddy County

Elevation (Show whether DF, RKB, RT, GR, etc.)  
3645GR

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Notify OCD 24 Hrs. Before Setting plug

1. POH w/ Tubing & pkrs.
  2. RIH spot 100' plug @ 2200 (perf. @ 2219 to 2337) Min. 25' x cement plug. TAG
  3. Perf. 5 1/2 @ 827 sqz. 100' plug woc tag
  4. Perf 5 1/2 @ 455 sqz. 100' plug (8 5/8 shoe @ 415') TAG
  5. Spot 30' plug @ surface \* Perforate 5 1/2" csg 50'. Circulate cement to surface.
  6. Cut off well Head install hole marker
- Inside a outside 5 1/2" casing.

\* Notice N.M.O.C.D. to witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE \_\_\_\_\_ TITLE Agent DATE 01-04-01

TYPE OR PRINT NAME Wayne Brooks TELEPHONE NO. 915 5807161

(This space for State Use)

APPROVED BY Mark Stollfeld TITLE Field Rep. II DATE 1/9/2001.

CONDITIONS OF APPROVAL, IF ANY: