

N. M. O. C. C. C.
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instruct. on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

028731 - B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

M. Dodd "B"

9. WELL NO.

30

10. FIELD AND POOL, OR WILDCAT

Squaw Lake

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 10, T-17-S, R-29-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3623 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Completion

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. Move in rotary rig. Spud.
2. Drill 11" hole to 520'. Run 8 5/8", 24#, J-55 to CP at 492'. Cnt w/300 ex reg. cnt. WOC 18 hrs. Test csg to 1000 psig for 30 min. OK. Cnt. circulated to surface.
3. Drill to TD of 2688'. Run 5 1/2" 14# & 17# csg to 2688. Cnt with 200 ex Inner Pssmx Test csg for 30 min at 1000 psig. OK.
4. Run Lane Wells PFC Log from 2660' (PSTD) to 2000'.
5. Perforated with 2 "E" gun bullets at each of the following intervals 2448, 2450, 2452, 2454, 2456, 2458, 2460.
6. Run 2 3/8" tubing w/Baker Model "AD" Packer to 2425.
7. Acidize perforated interval with 2000 gallons BDA.
8. Established injection rates into formation.
9. Installed injection well head.
10. Started water injection.

EFFECTIVE 4-1-70
SUN OIL COMPANY - DX DIVISION
NAME CHANGED TO
SUN OIL COMPANY

P. O. BOX 2880
DALLAS, TEXAS 75204

RECEIVED
JUN 20 1967
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

John Hastings

District Engineer

DATE June 16, 1967

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JUN 21 1967
R. L. BUCKWOLD
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.