					No	11	
					Reg	ng D	
					*	WELL OF	~ <i>.</i>
	5-USGS-ARI	ESIA	1-A.B.	CARY-MIDLA	ND	MAD WELL OFF	ICE CO
Form 9-331	1-R. J. SI	ARRAK-TULSA	1-FILF		Form Approv	/ed.	0,
Dec. 1973	UNITED STATES	;	5	LEASE	Budget Bure	au No. 42-R142	4
DEPARTMENT OF THE INTERIOR				IC-029418 (b)			
	GEOLOGICAL SURV	/EY	6.	IF INDIAN, ALLO	OTTEE OR TI	RIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)			LLS 7.	7. UNIT AGREEMENT NAME			_
			different 8	8. FARM OR LEASE NAME			
1. oil 💭 gas				Skelly Uni			
well X ³ well 2. NAME OF OPERA			9	WELL NO. 112			
Getty Oil Co	mpany		10	FIELD OR WILD			
3. ADDRESS OF OPE P. O. Box 73	RATOR 0, Hobbs, NM 8	8240	11	Grayburg J SEC., T., R., M.,		NO SUBVEY (
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17				AREA	7S-31E	do donier d	~~
below.) AT SURFACE: Ur	it Letter A 660)' FNL & 660'	FEL 12	COUNTY OR PA		STATE	
AT TOP PROD. IN AT TOTAL DEPTH:				Eddy	Ne	ew Mexico	
16. CHECK APPROPRI		TE NATURE OF I		API NO.		:	
REPORT, OR OTH	ER DATA		15	ELEVATIONS (S	SHOW DF,	KDB, AND W	D)
REQUEST FOR APPRO		EQUENT REPORT	OF:	3941' DF			-
TEST WATER SHUT OF FRACTURE TREAT							
SHOOT OR ACIDIZE REPAIR WELL				OTE: Report res	ECE	Depution or zo	 Me
PULL OR ALTER CAS MULTIPLE COMPLETE				change on Fo	orm 9-330.) .	1079	•
CHANGE ZONES ABANDON					APR 2	1979	N.
(other) Casing (Connections			Ű	J. BEULU	NEW MEXICO	л. }
17. DESCRIBE PROPO	SED OR COMPLETED	OPERATIONS (CI	early state all	pertinent details	ARIE BIVE	nertinent dat	
measured and true	d date of starting any e vertical depths for all	markers and zone	s pertinent to	onally drilled, giv this work.)*	e subsurfac	e locations a	nd
Riser on <u>8</u>	5/8" OD and 5	1/2" OD cas	ing brough	nt to surfac	æ.	• -	
						? E D	EIVE
Inspected by	B. W. Weaver	(NMOCC) on			•	MAY	2 1979
Inspected by	/ Nike Williams	(NMOCC) on			•	1001	~ 1379
Inspected by	y James Brasfie	ld (USGS) on			· ·	O. (C. C.
Inspected by	y Bird Jones (U	SGS) on	APR 2	5 1 97 9	6		, UFFICE
Subsurface Safaty Vali	e: Manu. and Type				Set C		F 4
 Bubsurface salety value 18. Thereby certify that 				····· <u>····</u>	_ Set @		FT.
SIGNED			a Sunt	DATE APR	0 -		