

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT -" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Phillips Petroleum Company

3. Address and Telephone No.

4001 Penbrook Street, Odessa, TX 79762 915/368-1488

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650' FNL & 330' FWL OF SECTION 35, T-17-S, R-30-E

NM OIL CONS COMMISSION
Drawer DD
Artesia, NM, FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

NM 0558579

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

FEDERAL 1

9. API Well No.

30-015-21062

10. Field and Pool, or exploratory Area

GRAYBURG JACKSON

11. County or Parish, State

EDDY NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRU DDU. NU BOP.
2. LAY DOWN ANY PRODUCTION EQUIPMENT. RUN SCRAPER TO 3075' WITH 2-3/8" WORKSTRING.
3. SET CIBP @3050' WITH WORKSTRING. CIRC. 5-1/2" CASING WITH 9.5 PPG MUD LADEN FLUID.
4. SPOT PLUG #1 W/25 SX CMT F/2950' T/3050' (GRAYBURG).
5. SPOT PLUG #2 W/25 SX CMT F/2434' T/2534' (QUEEN).
6. PERFORATE 5-1/2" CASING AT 553'. PLUG #3 W/150 SX CMT F/553' T/3'.
7. CUT OFF WELLHEAD. INSTALL MONUMENT MARKER AND PERFORM RECLAMATION WORK.

14. I hereby certify that the foregoing is true and correct.

Signed

[Signature]
Title SUPERVISOR, REG. AFFAIRS

Date 11/04/94

(This space for Federal or State office use)

Approved by

[Signature]
(ORIG. SEC.) JOE G. LARA

Title

PETROLEUM ENGINEER

Date

11/7/94

Conditions of approval, if any:

See attached.