

NEVADA COPY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-7748

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different formation.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ JUN - 5 1978

2. NAME OF OPERATOR
Kewanee Oil Company

3. ADDRESS OF OPERATOR
P. O. Box 3786, Odessa, Texas 79760

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
Unit M, 990' FWL & 990' FSL, Section 12, T-17-S, R-29-E,
Eddy County, New Mexico

7. UNIT AGREEMENT NAME
Square Lake 12 Unit

8. FARM OR LEASE NAME
Tract 2

9. WELL NO.
2

10. FIELD AND POOL, OR WILDCAT
Square Lake (G-SA)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Section 12 T-17-S, R-29-E

14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3640' G.L.

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☒ Perforate & Treat

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Perforated 5-1/2" casing @ 2427', 30', 35', 38', 42', 50', 97', 2500' and 2503' with 1 shot each and spotted 200 gallons 15% NE acid. Treated perforations from 2497' to 2503' with 200 gallons 15% NE acid @ 1500 psi @ 2 BPM.

Treated perforations from 2427' to 2450' with 450 gallons 15% NE acid @ 2000 psi @ 3/4 BPM. ISIP 1700 psi. 10 minute SIP 1700 psi.

Current well test - 2.7 BO & 19.8 BW.

18. I hereby certify that the foregoing is true and correct

SIGNED E. J. Stinson

TITLE District Manager

DATE June 1, 1978

(This space for Federal or State office use)

APPROVED BY Quentin Hall

TITLE ACTING DISTRICT ENGINEER

DATE JUN 05 1978

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations, when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1983-O-685229

647-485